REPORT TO: SCRUTINY COMMITTEE – 24TH MARCH, 2022

REPORT ON: ROOF TILE FIXINGS TO DOMESTIC PROPERTIES - BACKGROUND

INFORMATION

REPORT BY: HEAD OF DEMOCRATIC AND LEGAL SERVICES

REPORT NO: 103-2022

1.0 PURPOSE OF REPORT

1.1 The purpose of this Report is to provide background information regarding Roof Tile Fixings to Domestic Properties to aid scrutiny.

2.0 RECOMMENDATIONS

2.1 It is recommended that the Committee note the background information provided at Appendices 1 to 4.

3.0 FINANCIAL IMPLICATIONS

3.1 None.

4.0 MAIN TEXT

4.1 Roof Tile Fixings to Domestic Properties

At its meeting on 22nd November 2021 the Policy and Resources Committee:-

- (i) noted the findings of the review, and that officers had concluded that the roof installations during this period did not meet best practice as set out in the British Standards:
- (ii) approved works to be undertaken to bring the affected roofs up to the standard recommended in British Standards at an estimated cost of £4.4m, inclusive of an allowance for Housing staff resourcing and professional fees;
- (iii) noted the corrective action and compliance monitoring measures set in place to ensure specification, execution and managing of construction works were undertaken to appropriate industry standards;
- (iv) noted that, as part of the corporate Legislative and Regulatory Updates assignment being carried out by Internal Audit, current arrangements in place, within the Design and Property Division, Construction Services and Housing, would be reviewed to ensure that relevant new or changed legislative and regulatory requirements were identified and, where appropriate, addressed timeously;
- (v) required officers to obtain an independent and external view, in addition to the internal audit process, to provide assurance that any and all failures identified within the report and any subsequent findings that stemmed from the internal audit investigations, were fully and unquestionably addressed. Such work should reinforce accountability, transparency and confidence in service delivery. This work to be completed as soon as possible with an update on progress by the end of February, 2022;
- (vi) instructed officers to provide a detailed overview of how the corrective actions detailed in section 5.3 of the report differed from those undertaken during the roofing work carried out between 2015 and 2019; and
- (vii) noted that the report would be referred to a future Scrutiny Committee.

(Article XV of the minute of meeting of the Policy and Resources Committee of 22nd November, 2021 – Report No 335-2021 refers).

Attached at Appendices 1 to 4 is background information to aid scrutiny.

5.0 POLICY IMPLICATIONS

This report has been subject to an assessment of any impacts on Equality and Diversity, Fairness and Poverty, Environment and Corporate Risk. There are no major issues.

6.0 CONSULTATIONS

6.1 The Council Management Team were consulted in the preparation of this report.

7.0 BACKGROUND PAPERS

7.1 None.

ROGER MENNIE, Head of Democratic and Legal Services

DATE: 16th March, 2022

APPENDIX 1

Roofs Information for Bailie Macpherson - page 5

"A" series documents refer to Camperdown 2nd Development Phase 2 produced by DCC Architects at Pre-Contract Stage:

Ai – Roof & Floorplans	Page 6
Aii – Elevations	Page 7
Aiii –Specification Notes	Page 8
Aiv –Location Plan	Page 9
Av –Eaves Detail	Page 10
Avi –Verge Detail	Page 11
Avii – Party Wall Detail	Page 12
Aviii – Soil Vent Pipe Detail	Page 13

"B" series documents refer to St Mary's 10th Development Phase 3 produced by DCC Architects at Pre-Contract stage:

Bi – Roof Plans & Specification (Building A) Bii – Minutes of Pre-start Meeting	Page 14 Page 15
Biii – Russell Roof Tiles Fixing Specification	Page 19
Biv – Location Plan	Page 20
Bv – Cloaked Verge Detail	Page 21
Bvi – Roof Plans & Specification (Building B)	Page 22
Bvii – Elevations (Building A)	Page 23
Bviii – Eaves Detail	Page 24
Bx – Separating Wall / Roof Junction Detail	Page 25
Bxi – Ridge Detail	Page 26
Bxii – Chimney Capping Detail	Page 27
Bxiii – Front and Back Chimney Detail	Page 28
Bxiv – Chimney Refurbishment Detail	Page 29
Bxv - Chimney Flashing Isometric Detail	Page 30

"C" series documents refer to St Mary's 10th Development Phase 3 produced by DCC Clerk of Works, DCC Construction Services or DCC Architects during Construction:

Ci – Clerk of Works Weekly Report	Page 31
Cii – Photograph showing stamped tiling batten (Clerk of Works)	Page 33
Ciii – Photograph showing double-nailed roof tile (Clerk of Works)	Page 34
Civ – Request for Information (Construction Services)	Page 35
Cv – Architects Instruction	Page 36
Table of Contents	Page 37

This page is intentionally left blank

ROOFS INFORMATION FOR BAILIE MACPHERSON

Design Information

Prior to the 2015 update to BS 5534 it was customary for the Architects team to specify the fixing of concrete tiles to be "in accordance with the manufacturer's specification". This ensured that, should a different roof tile be installed from that specified, that the manufacturer would be consulted by the Contractor to request the relevant fixing specification. This custom continued after the 2015 update to BS 5534 which sought to standardise practice across the EU by adoption of Eurocode standards for wind uplift calculations, resulting in more onerous fixing requirements for single-lap concrete roof tiles in the UK. Documents Ai, Aii, & Aiii date from May 2015 and demonstrate this specification as issued for Camperdown 2nd Development, Phase 2 roof replacement programme. Documents Aiv – Aviii show the other drawings included as part of the contract documents.

Updated Design Information

Since it came to light that the roof replacement projects had not been installed in accordance with the 2015 update of BS 5534, the design information (drawings and specification) provided to the Contractor has been updated to refer specifically to the latest version of BS 5534 and to note that the contractor is to obtain a site-specific fixing specification from the roof tile manufacturer, and that historic fixing practices are not to be used. Procurement regulations prevent the designer from specifying a manufacturer or particular product, therefore the actual specification of the roof tiles is not known to the designer until after the design information is produced and issued for tender. Document Bi is a drawing from a current roofing project – St Mary's 10th development phase 3, showing the updated specification.

Document Bii is a copy of the pre-start meeting minutes where it is noted the Contract Administrator asked Contract Services to obtain a copy of the site-specific fixing specification from the roof tile manufacturer. Contract Services confirmed the manufacturer to be Russell Roof Tiles and the tile to be Double Roman and asked the Contract Administrator to obtain the site-specific fixing specification from Russell Roof Tiles. All those who attended the meeting or gave apologies are copied into all project documentation.


Document Biii is a copy of the site-specific fixing specification obtained from Russell Roof Tiles and issued to the project team.

Documents Biv – Bxv show the extent of the layouts and construction details issued to the Contractor in the course of the design and delivery of the project.


Enhanced Clerk of Works Checking Procedures now in place

The above design information, pre-start meeting minutes, and site-specific fixing specification establish that historic fixing practices are not be used. This information is communicated to the whole project team by the issue of these documents.


The Clerk of Works visits the site regularly to inspect the progress of the works and produces a weekly report detailing his findings – see document Ci. As noted in this report, a digital photo record of the project in progress is retained by the Contractor. Image Cii shows a tiling batten stamped with the information required by BS5534, and image Ciii shows the concrete roof tile fixed to the tiling batten with two nails as required by BS 5534. During the project, requests for additional information are made in writing by the Contractor by the issue of an Request For Information (RFI) document – see document Civ. Confirmation of queries is via the RFI returned to the contractor, whereas variations to the contract specification or drawings require either a Clerk of Works Direction (which must be confirmed by an Architects Instruction) or an Architects Instruction – see document Cv, which is issued to the whole project team.



Ground Floor Plan







New Roof Titles

Marley Double Roman Single-Lap Concrete Roof Tiles

Colour: Old English Dark Red

Ridge Marley

Segmental Ridge Tile Colour: To Match Roof Tile

Cloak Verge Marley Double Roman

Cloak Verge Tite Colour: To Match Roof Tile Chimney

See Lead Sheet Manual Chimney Flashings and Details Code 4 or 5 Lead See DWGs 404 and 405

Chimney - Demolition Carefully Take Down Existing Redundant Chimney To Be Confirmed

Existing Cimney Examine Existing Chimney and Report Defects See Notes 400 and 401

Existing Expansion Pipe

Fit Ubbink WEP Pipe Colour and Profile to Match New Roof Tiles. **Extend Expansion Pipes** Where Required To Be Checked on Site

Existing Expansion Pipe Carefully Remove Redundant Expansion Pipes To Be Checked on Site

List of Addresses 18,32,38,1,7,9 Brownhill Place 7,14,18 Brownhill Street CON 7.13 Liff Crescent

1.5 JUN 2015

ISSUE

Support Services

Director.

ARCHITECTURAL SERVICES,

Camperdown 2nd Development Pitched Roof Replacement Phase 2

Checked/L File Ref. 15-51

Roof and Floor Plans

Drwg. No. 20(


BM TRADA


Patricia McIlquham


Rev. 7/05/15

City Architectural Services Officer, Floors 11/12 Tayside House, 28 Crichton Street, Dundee, DD1 3RQ. Tel Fax: 01382 433034









Gable Elevation Scale 1:100

Rear Elevation

Front Elevation

CONTE

1 5 JUN 2015

ISSUE

Expansion Pipe Fit Ubbink WEP Tile Colour and Profile to Match **New Roof Tile Existing Expansion Pipe** Carefully Remove Redundant **Expansion Pipes** To Be Checked on Site

S.V.P. and W.V.P. See Detail DWG 404

See Notes DWG 400 and 401

Abutment at Gable Wall

Carefully Cut a Neat Chase (Raggle) in Wall. Size Approx. 15x30mm For New Lead Sheet Flashings See Lead Details DWG, 406

Existing Chimney Examine Chimneys and Report Defects

New Roof Tiles Marley

Double Roman Roof Tiles Colour : Old English Dark Red **Eaves**

New Cellular PVC Fascia and Soffit See DWG. 402

Make Good Existing Render

Cloak Verge Tile and Cellular PVC Barge - Board Detail See DWG 403

S.V.P. and W.V.P. See DWG 404



Director.

Camperdown 2nd Development Pitched Roof Replacement phase 2

Elevations

Drwg, No. 300

Checked/f File Ref.

15-51

ARCHITECTURAL SERVICES, City Architectural Services Officer, Floors 11/12 Tayside House, 28 Crichton Street, Dundee, DD1 3RQ, Te



New Roof Tiles

Marley

'Double Roman'

Colour: Old English Dark Red Interlocking Concrete Roof Tiles See Manufacturers Printed Instructions

See Marley Technical Details

New Underlay

New Underlay - Protek non woven underlay on OSB sarking to replace Celotex Min. Horizontal Lap 100mm Min. Vertical Lap 150mm Min.

Counter Battens

Size: 38x25mm Treated timber Counter Batten Counter Batten Centres to Match Existing Rafter or Truss Centres where possible

Tile Battens

Size: 38x25mm Treated Timber Tile Batten

Tiling

Headlap Min. 100mm

Fixing

All Tiles Fixed with Tile Clip and Nail Where Possible See Marley technical Details

Ridge

Marley Ventilated Dry Ridge System
Mechanically Fixed with Rigid Sarking
See Marley Technical Details
Cut Back Underlay-Undertiling Felt and Sarking Boards
for Unobstructed Roof Ventilation
Min. 5mm gap for Roof Ventilation

Ridge Tile

Marley
Segmental Ridge Tile
Colour: Old English Dark Red
To Match Roof Tiles

Eaves

New Cellular P.V.C. Fascia and Ventilated Soffit Board See Detail DWG 402

Eaves

Standard Tile with Comb Filler

Eaves Protection System

Ubbink EPS

UPVC Colour: Black

See Ubbink Technical Details

Cloaked Verge

Marley

Cloaked Verge Tile System 'Double Roman'

See Marley Technical Details Colour: Old English Dark Red

To Match Roof Tiles

Cloak Verge Tite Fixed with Secret Fixing

Half Tile for Adjustment

See Cloak Verge and Cellular PVC Bargeboard

Detail DWG 403

Complete Verge Apex with Block End Ridge Tile

Existing Rain Water Gutter

Carefully Remove Existing Rain Water Gutters
Existing C.1. Gutters or UPVC To Be Checked on Site

Rainwater Goods

Marley

Deepflow UPVC Rainwater Gutter New Gutter Connected to Existing R.W.P.

Colour: Black

Remove all debris and Clean Gutters and Test for Leaks on Completion of Work

Soil and Vent Pipe and Waste Pipe See Detail and DWG 404 Existing Sarking - Fragile Roof Material
Celotex Sarking Boards

Carefully Remove Existing Celotex Sarking

New Sarking


Min, 15mm Thick Treated Timber Sarking Nailed to Existing Rafters

Gable / Wall and Roof Abutment


Abutment Flashing with Secret Gutter Code 5 Lead See Lead Details DWG 406 Fixing and Pointing of Lead Sheet Flashings


CONT

1 5 JUN 2015













Z



NOTE
CAREFULLY CUT OUT EXISTING
BRICKWORK AND FIX OUTRIGGER
SPROCKET PIECE AND MAKE GOOD
WALL HEAD BRICKWORK








Proprietary in-line tile vents to be installed as close to eaves as possible. Spacings shown are indicative only. Actual spacing of units is to be as appropriate to provide the

correct levels of ventilation. Lines of Rear of Building Bonding gutter flashing at Eaves height separating approx 5100mm junctions between new walls. All existing gutters to roofs being SVP RWP from FFL and retained roofs. replaced to be carefully removed and disposed of. Existing and new gutters to be cap ended where a water tight connection cannot be made. Additional RWPs to be installed where required. -Roof All chimneys to roofs Light Light being renewed to be Rooflights in roofs being renewed Roof | either demolished, or Ventilated to be removed and disposed of. Light Roof Pitches Light refurbished, subject —dry ridge. Approx 32° to confirmation. Detail` 402 Ridge height 00 00 approx 7700mm from FFL All chimneys serving properties being Detail \ / Detail \ / Detail \ re-roofed are to to be either demolished, 406 or refurbished, subject to confirmation. Cloak tiles or dry verge system to be fitted to verges. RWP RWP 6830 Approx 6580 Approx 6580 Approx 6830 Approx Front of Building No 39 St Clement Place No 37 St Clement Place No 35 St Clement Place No 33 St Clement Place Type D Type D Type D Type D Detail (not to be replaced) (not to be replaced) (not to be replaced) NB: Roof shown is the same as the following roof to be replaced: 27 St Clement Place Roof Plan @ 1:100

All junctions between separating walls and the underside of the roof to roofs being renewed are to be checked on site by the Contract Administrator.

Existing cast iron rain water goods at sections of roofs being renewed are to be replaced with new uPVC sections. Top sections of SVPs to be replaced as required to allow for new roof oconstruction.

All existing fascias to roofs being replaced to be carefully removed and disposed of and replaced with new uPVC. Junctions between retained and new fascias are to be finished with a uPVC junction trim. Existing concrete corbelled soffits to be retained. New section of uPVC soffit to be fitted at end of elevations and to wrap around gables.



SPECIFICATION NOTES

1. EXISTING BUILDING CONSTRUCTION:

The walls and chimneys are constructed in concrete blockwork. The roof is constructed in a timber structure and is finished with concrete

The chimneys are fitted with sectional concrete coping stones and clay

PREPARATION:

Carefully remove and dispose of existing tiles, roof vents, battens, and

Existing roof sheathing to be checked and notice given for any defective boards. Any loose boards to be adjusted to level and securely fixed. Punch in protruding fasteners and plane or sand to achieve an even surface. Moisture content: Not more than 22% at time of covering. Give notice if greater than 16%. If the roof is sheathed with wood fibre board this is to be completely removed and disposed of. Roof sheathing to be removed as required to allow for any fire proofing improvements. Carefully remove and dispose of all existing roof lights.

Carefully remove and dispose of the existing guttering, and fascias. Carefully remove the existing rainwater pipes. Where required to allow for roofing works, carefully remove and dispose of the SVPs at junction with roof. Extent of SVPs to be replaced to be agreed on site. The Contract Administrator is be notified upon the discovery of any rotten

Roof access and site set up are to be agreed with the Principal Designer

through the CPH&SP. The specification is to be read in conjunction with all project issue plans and documents. Any contradiction between the different sources of information provided is to be brought to the attention of the contract

CONSTRUCTION PHASE HEALTH AND SAFETY PLAN (CPH&SP): The contractor is to submit a construction phase health and safety plan prior to the works being permitted to start on site. Dundee City Council City Development are to provide a Pre Construction Information Pack (PCIP) along with the tender documents which provides

ASBESTOS:

administrator.

Dundee City Council City Development are to arrange for an asbestos survey to be provided for the areas of the buildings which are affected by

the key information required for the contractor to compile the CPH&SP.

Downtaking works are not permitted to start on site by the contractor until the asbestos survey has been received. The contractor is to contact the Contract Administrator if they have any asbestos related concerns in relation to the building.

5. ROOF SHEATHING/ SARKING:

Where sheathing boards are to be patched, the replacement sections are to be the same thickness as the existing. Where the whole roof sheathing is to be replaced the new boards are to be 12mm thick OSB3 roof sheathing boards securely fixed through the roof structure.

UNDERLAY:

-All specifications to be read as "EQUAL AND APPROVED"

New underlay is to be a high resistance non-breathable membrane in accordance with BS 5534 Part 1 and is to be installed in accordance with

manufacturers written instructions. Underlay to be laid parallel to eaves, maintaining consistent tautness with vertical laps not less than 100mm wide (or width as recommended by the manufacturer), covered with tile counter battens supports or sealed using proprietary sealant as recommended by the underlay manufacturer. Horizontal laps of 150mm specified.

Underlay to be lapped with exposed eaves skirt to provide fully weathertight finish.

Underlay to be handled carefully to prevent tears and punctures. Penetrations: Use proprietary underlay seals or cut underlay to give a watertight fit around pipes and components. Where pipes and other components penetrate the underlay, cut neatly and accurately and turn flanges up to give a tight, watershedding fit. Ventilation paths not to be obstructed.

Note: If tear occurs repair with adhesive tape, or cut new section of underlay, remove torn section by cutting close to sides of rafters, slide up new section of underlay, staple sides to rafters.

7. NEW ROOF TILES:

roof tiles with a smooth finish. All roof tiles are to be mechanically fixed in accordance with the manufacturers instructions and in accordance with the latest edition of BS The contractor is to contact the roof tile manufacturer to obtain a site

New roof tiles are to be concrete single lapped interlocking Double Roman

specific fixing specification. The contractor is not to use historic experience as a basis for the fixing specification. All head lap distances are to be be in accordance with the manufacturers written instructions and based on the pitch of the roof. The contractor is to notify the Contract Administrator if the roof pitch is less than anticipated and too shallow a pitch for the roof tile.

8. ROOF RIDGE:

The ridge is to be a proprietary mechanically fixed ridge ventilation system providing a continuous weathertight air path from the roof void to the outside. The system is to provide ventilation to BS 5250:2011 and to comply with BS 5534:2014 for mechanical fixing. The ridge tiles are to be half round, and in a colour, material, and finish to match the roof tiles.

approved installation in accordance with manufacturers requirements

The verge of the roof is to be finished with Double Roman cloak verge tiles. The tiles are to be concrete in a colour and finish to match the roof

The tiles are to be fixed with proprietary clips and fixings to provide

An undercloak is required to be installed between the battens and structure, touching the inside face of the tile to prevent bird ingress. The verge tiles are to be secret fixed.

The components that make up the Cloaked Verge System must comply with BS EN 490: 2011, BS EN 1304: 2013 and the latest revision of BS 5534. The cloak tiles are to be compatible with the roof tiles and are to be installed in accordance with the manufacturers instructions and in accordance with the latest edition of BS 5534. The verge overhang is to be the same width at both sides.

10. EAVES:

Rafter trays are to be installed over the rafters to ensure a continuous 50mm free air path is provided through to the the roof ridge. A proprietary black PVCu rigid eaves support tray is to be fitted at the eaves. The eaves support tray is to be lapped a minimum 150mm. A timber tilting fillet is required below the support tray if the roof pitch is below 20°.

The roof underlay is to overlap the eaves skirt.

11. CAVITY CLOSERS:

Where the wall heads are not currently closed they are to be fitted with a cavity closer. New cavity closers are to be manufactured from rock mineral wool with a non-combustible classification, and is to be enveloped with a polythene sheet. The cavity closer is to be tightly friction fitted at the wall head to close the

The cavity closer is to have a 60 minute fire integrity rating.

12. FIRE STOPPING

Additional fire stopping is to be undertaken to the existing separating walls only when instructed by the Contract Administrator following a site assessment. The Contractor is to notify the Contract Administrator when the roof is ready to assess any fire stopping requirements. Where fire stopping is required: Fill space over top of wall with layers of rock mineral quilt with a non-combustible classification so that it is tightly compressed between the wall head and underside of the rigid sarking/sheathing board. Tuck edges of quilt between edges of wall and adjoining rafters.

Between the roof tiles and sarking/sheathing, lay 300mm wide pads of mineral fibre quilt thick enough to seal all gaps and cut to fit snugly between the battens and counter battens. Fix in position with continuous self adhesive tape from ridge to eaves before installing the tiles. At boxed eaves completely seal air paths in the plane of the separating wall with wire reinforced rock mineral wool quilt with a non-combustible classification. Rock mineral wool sections are to be one 50mm thick piece nailed to either side of the rafter and carefully cut to shape to provide fire stopping.

13. ROOF SPACE VENTILATION:

Eaves and ridge ventilation is to be installed to provide ventilation into the roof space complying with the latest edition of BS 5250. At the eaves, proprietary in-line vents are to be installed as close to the eaves as possible to provide the eaves ventilation. In-line vents are to be in a colour and profile to match the roof tiles and are be finished in the same plane as the roof tiles ie- no 'mushroom' type tile vents permitted. 10000mm²/m continuous ventilation is to be provided at the eaves. The ridge ventilation is to be provided by installing a ventilated dry ridge system providing 5000mm²/m continuous ventilation. Ventilation is to be in accordance with BS 5250: 2002 and installed in accordance with manufacturers instructions and in accordance with the latest revision of BS 5544.

14. GUTTERS and RWPs:

New gutters are to be PVCu 110mm x 75mm semi eliptical gutters with high flow capacity. The gutters are to be fixed to the fascias using proprietary PVCu fixing brackets. Gutters are to be kitemarked to BS EN 607 and BS EN 1462. New RWPs are to be circular PVCu i n size to match existing. New pipework is to be kitemarked to BS EN 1329-1. Gutters and pipes are to be kept free of debris and cleaned out at completion. Gutters to be tested for leaks upon completion. Retained and new gutters are to be cap ended at any junctions between retained and new roofs. New RWPs are required where an outlet has been removed from a run due to cap ending gutters.

15. SVPs:

New sections of uPVC SVPs are to be installed in colour and size to match existing. New pipe work and fittings to be kitemarked to BS EN 1329-1. New pipe work to be bent round the outside of the soffits and fascias. All support brackets are to be uPVC with suitable number of brackets required to provide adequate support for new sections of pipe.

Colour of gutters and RWPs is to match existing.

16. NEW SOFFITS AND FASCIAS:

New fascias are to be formed with cellular PVCu. All extruded cellural PVCu profiles are to be manufactured in accordance with BS 7619:2009. The boards are to be of a suitable depth for the application. The fascia boards are to be approx 16mm.

The boards are to be jointed using proprietary panel joints. Joints locations are to be agreed on site.

The fascias are to be mechanically fixed in accordance with the manufacturers instructions. All fixings are to be A4 marine grade and comply with BS EN ISO 3506: 1+2, or austentitic stainless steel grade 316. Any exposed fixing heads are to be plastic coated in a colour to match the boards. All fixings are to be evenly spaced.

The new fascias are to be installed in accordance with the 'British Plastics Federation Code of Practice For The Installation of Cellular PVC-U (PVC-UE) Roofline Systems'

Where a junction is required between retained and new fascias, the existing material is to be carefully cut at the required junction location and the junction finished with a uPVC junction trim. The fascia colour is to be black or anthracite grey- the final colour is to be confirmed. The new fascias are to have a hockey stick type return at the bottom edge to mask the edge of the existing concrete soffit.

The existing sectional concrete soffits/ wall heads are to be be retained.

All timber must be obtained from fully verifiable Forest Stewardship Council FSC or Pan European Forest Certification PEFC. Any timber used for support work or battening is to be of sound quality and preservative treated in accordance with BS 8417. All timber used for closing openings is to be structural grade C16. Counter battens are to be 50 x 25mm timber sections. Counter battens are to be securely fixed through the rafters.

Tile battens are to be 38×25 mm timber sections for 450mm rafter centres, and 50 x 25mm timber for 600mm centres. Battens should span at least three rafters and be at least 1.2m long. No more than one in four battens should be joined over one truss for gauges over 200mm. For gauges less than 200mm there can be a maximum of three consecutive joins in any twelve battens. Fixings to be suitable for the wind load resistance as set out in BS 5534 Annex H7.

100 x 50mm (Nom) timber sections are to be used to close off the roof light openings.

18. LEAD FLASHINGS:

All lead works to be in accordance with BS 6915 and latest edition of 'Rolled lead sheet. The complete manual' published by the Lead Sheet Association. All lead installers to be trained in the application of lead coverings/ flashings and to submit records of experience on request. Flashings to be pre-formed by measuring, marking, cutting and forming prior to assembly wherever possible. Marking out not be carried out using scribers or other sharp instruments without approval. Bossing and forming to provide straight and regular bends, leaving sheets free from ripples, kinks, buckling and cracks.

Finished work to be fully supported, adequately fixed to resist wind uplift but also able to accommodate thermal movement without distortion or stress. Finished work to be protected to prevent staining, discolouration, and damage by subsequent works.

Building paper is to be fitted below all new lead work. All lead is to be treated with patination oil. Patination oil to be applied to ALL new lead work. Patination oil is to be applied as soon as practical, apply a smear coating to lead, evenly in one direction and in dry conditions.

19. BONDING GUTTER:

Junctions between retained and new roofs are to be weathered using a proprietary dry fix bonding gutter. Edges of existing roof sheathing to retained roofs to be neatly cut to allow

for installation of new bonding gutter detail. Gutter to be manufactured from GRP and to be BS 5534 compliant. Central upstand height of gutter to suit roof tile type. Bonding gutter to be positioned allow the roof tile bond to be maintained

and using a tile and a half as required. Bonding gutter to overhang 50mm in to rain water gutter. Joints in bonding gutter are to be lapped a minimum length in accordance with the manufacturers recommendations. When mechanically fixing the slates or tiles to the side of the bonding gutter care should be taken not to make any punctures to or between the water channels.

A code 4 lead saddle is to be fitted over the bonding gutter ridge joint in accordance with the latest edition of BS 6915.

20. CHIMNEYS REMOVAL (Subject to Confirmation): The client is to check with all tenants whether the the chimneys are operational and advise whether the chimneys are to be removed. If confirmation is received, the chimneys are to be carefully taken down along with any copes, chimney, pots, lead flashings, etc. All demolition works are to be undertaken in accordance with BS 6187. Contractor to provide full Risk Assessments and Method Statements to the Principal Designer for approval prior to the start of any demolition

21. CHIMNEY REFURBISHMENT (Where Full Removal is Not Required): The chimney copes are to be re-pointed as required. If any copes are damaged beyond repair, the contractor is to notify the Contract Adminstrator to allow an inspection to be made. All chimney pots are to be checked for stability. Any loose haunching is to be removed and any loose chimney pots re-haunched to secure. All boss render is to be carefully removed from the chimneys. All areas where the render has been removed are to be patched with undercoat render to bring level. All existing lead flashings are to be removed and new lead flashings installed. A bell cast bead is to be tied in with the lead chimney flashings, and stainless steel expanded metal lath is to be mechanically fixed over the existing render before a two layer dry dash render is applied over the whole chimney.

22. TV AERIALS & SATELLITE DISHES:

Aerials and satellite dishes are to be checked for operation. Any redundant aerials are to be permanently removed subject to confirmation from the Contract Administrator.

Any aerials and satellite dishes which are to be retained are to be temporarily removed and fitted to the scaffolding by a qualified aerial contractor. Residents are to be consulted throughout this process to ensure that a good reception is retained at all times. At the completion of the works when any aerials and satellite dishes are re-positioned to their permanent location the residents are again required to be consulted to ensure a good reception is received.

All fixing brackets, and LNB connections, are to be renewed as required re-fixing the dishes and aerials.

23. COLD WATER STORAGE TANKS:

Check existing cold water storage tank in roof space and report Extend overflow pipe from cold water storage tank as required.

Silicone sealant to be low modulus type to BS 5889 type A gun applied

25. DISCHARGE PIPE TERMINATIONS AND OVERFLOW PIPES: Any overflow or discharge pipes are to be checked for operation. Any redundant pipes are to be permanently removed.

26. WASTE MANAGEMENT: The contractor must adopt a waste management system. Waste management is to be carried out on or off site and must be confirmed within the CPH&SP.

General:

All elements of the roof are to be fully installed in accordance with the

manufacturers written instructions.

All workmanship standards to be in accordance with BS 8000-6. All roof tiling and slating to be installed in accordance with the latest revision

All roof to be fully cleaned before the removal of the scaffolding. All windows, including cills/frames etc, are to be fully cleaned as the scaffolding is being removed. The contract administrator is to be given notification for inspection prior to the scaffolding being removed.

Any defects in relation to any part of the building services terminations noticed by the contractor are to be brought to the attention of the Contract Administrator.

Contractor to ensure all roofs are watertight at the end of each working day. The contractor will be held responsible for any water ingress into the building as a result of the ongoing works.

All areas are to be fully cleared of any materials and equipment prior to

Revision Description SVPs confirmed to be replaced at junction with roof only. 17/10/20 File Ref. Proposed Roofing Works 19-514 St Marys 10th Development Phase 3 DCC ID Jundee City Council Roof Plan & Specification Drwg No. Buildings B City Development Design & Property Division 1:100 @ A1 Mar 20

City Development, Dundee House, 50 North Lindsay Street, Dundee, DD11LS Tel: 01382 434000

Miller Switzer = =	F 009 M	inute of Pre S	tart Meeting	
Project Number	14		19-514 & 19-545	
Project Title			arys 10th Dev Ph3 - Ro arys 8th Dev Ph3 - Ro	
	O	nly fill in sections	in blue.	
Meeting Place:			Date:	Time;
EDCS Conference	Room- Clepingtor	n Road	02/09/20	11:00
Contract Letter of Acceptance Date:		Contract Possession Date:	Contract Completio	Contract Period:
18/11/20		14/06/21 (TBC)	TBC	TBC
Present:				
Name	Initials	Organisation		Title
	80 BAT 15	City Development		Architectural Technician
A CAN THE STATE OF	(B)	EDCS		Site Mainager
25 to ()	150 100	EDCS		Quantity Surveyor
11.20 pt 22.20 pt 22	32	EDCS &		Contract Manager
		HAMU		Project Officer
Apologies:				- Annual Company of the Company of t
Name	BAA E	Organisation		Title
The second of th	0.6942	EDCS		Contracts Surveyor
	9,000	EDCS		Tenant Llaison Officer
	6	City Development	AND POSTERNATION	Quantity Surveyor
		City Development	NA STATE OF SHIPE	Quantity Surveyor
	2000年	City Development	位于古诗研究的张安斯	Senior Clerk of Works
	11 21/20	City Development		Clerk of Works
	6120	City Development		Principal Designer

TEM	MINUTE	···		ACTIO
1 50	Project Intr	oduction		
1.1.	Under the term	s of the contract, the A	Architect is	CLA CONTRACTOR
1.2.	The following p	personnel as being resp	ponsible for the running of the contract.	
	Title		Name Tel, No.	
	Meeting Chair	Person	200 12 12 12 12 12 12 12 12 12 12 12 12 12	34
	Project Admini	strator		
	Principal Desig	gner	2구 보고 한 조건이	25
	Structural Engi	ineer	TBC (if applicable)	44
	Quantity Surve			gò
	Quantity Surve	eyor		7
	Clerk of Works			
	Contract Mana	nger	110,7,150	2457 267.70 110005
	Site Agent			0.45 6.55
	Contractor Qua	antity Surveyor		18
	Client Represe			
	Confirm tha	t Contractor will have a	a person in Charge as per JCT 2005 Local Authority Edition with amendments identify him.	
]	a moze-ceu v suvolizacio	NAME OF THE PROPERTY OF THE PR	
1.3	Name	The state of the state of	1000000000000000000000000000000000000	
1.3,	1 -	elephone Numbers 2 of		310
	First No		Second No	
		mercency (outwith office	e hours) telephone number of contact nerson, i.e., Joh Title. Name and numbe	er - 1
	Record the er	mergency (outmer once	e hours) telephone number of contact person, i.e. Job Title, Name and number	***
		margancy (oderati onto		
	Name	morganity (datasets only	Title Number	
		morganoy (outman onle		
2	Name	entract Issues	Title Number	
2	Name Project Co		Title Number Site Agent	
	Project Co Is Appendix is	entract Issues sued with Agenda agre	Title Number Site Agent	
2.1	Project Co Is Appendix is If no give action	entract Issues sued with Agenda agre	Title Number Site Agent eed by all parties es with the appendix to be raised with	0
2.1	Project Co Is Appendix is If no give action (Appendix Iter Clement Place	entract Issues sued with Agenda agree on required:- Any issue on AP1.2) confirmed e removed from project	Title Number Site Agent eed by all parties es with the appendix to be raised with contract drawings had been issued for both contracts. confirmed 12 St 19-514 covered by Al no 02. Al issued to change cloak tiles to dry verges and	O
2.1	Project Co Is Appendix is If no give action (Appendix Iter Clement Place	entract Issues sued with Agenda agree on required:- Any issue	Title Number Site Agent eed by all parties es with the appendix to be raised with contract drawings had been issued for both contracts. confirmed 12 St 19-514 covered by Al no 02. Al issued to change cloak tiles to dry verges and	O
2.1	Project Co Is Appendix is If no give action (Appendix Iter Clement Place	entract Issues sued with Agenda agree on required:- Any issue on AP1.2) confirmed e removed from project fits and fascias to white	Title Number Site Agent eed by all parties es with the appendix to be raised with I contract drawings had been issued for both contracts. confirmed 12 St t 19-514 covered by Al no 02. Al issued to change cloak tiles to dry verges and a.	O
	Project Co Is Appendix is If no give action (Appendix Iter Clement Place to change soft	entract Issues sued with Agenda agree on required:- Any issue on AP1.2) confirmed e removed from project fits and fascias to white	Title Number Site Agent eed by all parties es with the appendix to be raised with I contract drawings had been issued for both contracts. confirmed 12 St t 19-514 covered by Al no 02. Al issued to change cloak tiles to dry verges and a.	O All
2.1.1	Project Co Is Appendix its If no give actic (Appendix Iter Clement Place to change soft (Appendix Iter Confirm date	entract Issues sued with Agenda agree on required:- Any issue on AP1.2) confirmed e removed from project fits and fascias to white on AP1.8 to check we of possession and Conf	Title Number Site Agent eed by all parties es with the appendix to be raised with I contract drawings had been issued for both contracts. confirmed 12 St t 19-514 covered by Al no 02. Al issued to change cloak tiles to dry verges and a.	O All
2.1.1	Project Co Is Appendix is If no give action (Appendix Iter Clement Place to change soft (Appendix Iter	entract Issues assued with Agenda agree on required:- Any issue on AP1.2 confirmed a removed from project fits and fascias to white on AP1.8 to check we of possession and Contany.	Site Agent Site Agent Peed by all parties Ses with the appendix to be raised with Contract drawings had been issued for both contracts. Confirmed 12 St 19-514 covered by Al no 02. Al issued to change cloak tiles to dry verges and the owner of the contract of the co	O All
2.1.1	Project Co Is Appendix its If no give action (Appendix Iter Clement Place to change soft (Appendix Iter Confirm date divergence if	entract Issues sued with Agenda agree on required: Any issue on AP1.2) confirmed e removed from project fits and fascias to white of possession and Contany. Start Date: 14/06/21	Title Site Agent Peed by all parties Es with the appendix to be raised with It contract drawings had been issued for both contracts. Confirmed 12 St to 19-514 covered by Al no 02. Al issued to change cloak tiles to dry verges and the sum of the sum	O All
2.1.1 2.1.2 2.2.	Project Co Is Appendix is If no give action (Appendix Iter Clement Place to change soft (Appendix Iter Confirm date divergence if Date Confirm that (entract Issues sued with Agenda agree on required:- Any issue on AP1.2) confirmed on the removed from project fits and fascias to white of possession and Contany. Start Date: 14/06/21 Guarantees, Bonds and	Title Site Agent Site Agent Peed by all parties es with the appendix to be raised with Contract drawings had been issued for both contracts. Confirmed 12 St 19-514 covered by Al no 02. Al issued to change cloak tiles to dry verges and all one of the contract Completion — state also Bills of Quantities dates and reasons for Completion Date: TBC Insurances to comply with the contract are in place — a sight of these is	O All
2.1.1	Project Co Is Appendix is If no give action (Appendix Iter Clement Place to change soft (Appendix Iter Confirm date divergence if Date Confirm that (entract Issues sued with Agenda agree on required: Any issue on AP1.2) confirmed e removed from project fits and fascias to white of possession and Contany. Start Date: 14/06/21	Title Site Agent Peed by all parties Sees with the appendix to be raised with Contract drawings had been issued for both contracts. Confirmed 12 St t 19-514 covered by Al no 02. Al issued to change cloak tiles to dry verges and all the contract Completion — state also Bills of Quantities dates and reasons for Completion Date: TBC Insurances to comply with the contract are in place — a sight of these is r.	O All
2.1.1 2.1.2 2.2.	Project Co Is Appendix is If no give action (Appendix Iter Clement Place to change soft (Appendix Iter Confirm date divergence if Date Confirm that Crequired by the	entract Issues sued with Agenda agree on required:- Any issue on AP1.2) confirmed on the removed from project fits and fascias to white of possession and Contany. Start Date: 14/06/21 Guarantees, Bonds and	Site Agent Site Agent Site Agent Peed by all parties es with the appendix to be raised with Contract drawings had been issued for both contracts. Confirmed 12 St 19-514 covered by Al no 02. Al issued to change cloak tiles to dry verges and all other projects are notifiable Intract Completion — state also Bills of Quantities dates and reasons for Completion Date: TBC Insurances to comply with the contract are in place — a sight of these is r.	O All
2.1.1 2.1.2 2.2.	Project Co Is Appendix its If no give action (Appendix Iter Clement Place to change soft (Appendix Iter Confirm date divergence if a change soft) Date Confirm that Confi	entract Issues assued with Agenda agree on required:- Any issue on AP1.2) confirmed a removed from project fits and fascias to white of possession and Contany. Start Date: 14/06/21 Guarantees, Bonds and he Project Administrator ees, Bonds and Insurantion required:-	Title Site Agent Peed by all parties Sees with the appendix to be raised with Contract drawings had been issued for both contracts. Confirmed 12 St. 19-514 covered by Al no 02. Al issued to change cloak tiles to dry verges and all with Whether projects are notifiable Intract Completion — state also Bills of Quantities dates and reasons for Completion Date: TBC Inces are in place YES Note: YES Note: TBC TBC TBC TBC TBC TBC TBC TB	O All
2.1.1 2.1.2 2.2.	Project Co Is Appendix its If no give action (Appendix Iter Clement Place to change soft (Appendix Iter Confirm date divergence if Date Confirm that of required by the Guarante If no give action Make it clear	entract Issues Issued with Agenda agree on required:- Any issue on AP1.2) Confirmed or removed from project fits and fascias to white of possession and Contany. Start Date: 14/06/21 Guarantees, Bonds and the Project Administrator theses, Bonds and Insurantion required:- To the Contractor tha	Site Agent Site Agent Peed by all parties Pes with the appendix to be raised with Contract drawings had been issued for both contracts. Confirmed 12 St 19-514 covered by Al no 02. Al issued to change cloak tiles to dry verges and the contract Completion — state also Bills of Quantities dates and reasons for Completion Date: TBC I completion Date: TBC I completion Date: TBC TBC I completion Date: TBC TBC TBC TBC TBC TBC TBC TBC	O All
2.1.1 2.1.2 2.2.	Project Co Is Appendix its If no give action (Appendix Iter Clement Place to change soft (Appendix Iter Confirm date divergence if Date Confirm that of required by the Guarante If no give action Make it clear	entract Issues Issued with Agenda agree on required:- Any issue on AP1.2) Confirmed to remove from project fits and fascias to white of possession and Confany. Start Date: 14/06/21 Guarantees, Bonds and the Project Administrator the Contractor that the contract - write a	Title Site Agent Peed by all parties Sees with the appendix to be raised with Contract drawings had been issued for both contracts. Confirmed 12 St. 19-514 covered by Al no 02. Al issued to change cloak tiles to dry verges and all with Whether projects are notifiable Intract Completion — state also Bills of Quantities dates and reasons for Completion Date: TBC Inces are in place YES Note: YES Note: TBC TBC TBC TBC TBC TBC TBC TB	O All

2.4.	Confirm whether the Contractor is a Principal Contractor under the Regulations.		YES	NO	
	If no give action required:-				
2.5.	Confirm whether or not an Asbestos Register is available.		YES	NO	
	If no give action required:- No asbestos register is available for the buildings. The contra survey reports for the buildings confirmed some of the surveys were deemed unsuit been taken confirmed he had e-mailed the asbestos surveyors to raise the concerns surveyors and advise.	it <u>able</u> a:	as received a s no samples o chase feedb	had	
2.6	Confirm Contractor's site management has competency in asbestos awareness. If no give action required:-		YES	NO	
3	Project Site Issues		11.78		
3.1.	Detail the site – as described in contract documents. If no give action required:-		YES	NO.	
3.2.	Confirm that the site is available to the Contractor.		YES	NO	
	If no give action required confirmed he would issue letters to tenants and neighbouthe works.	urs con	firming the da	tes for	1.50-4-65
3.3	Establish position of site sign-board.		YES	NO	
	If no give action required:- It was agreed that a Housing banner would have to be display scaffold frame could be erected for fixing the display. Final location and support for the required.			gested a . Al	
3.4	Is site office required?		YE	NO	
	If required what is address/location of site accommodation :-		1779/23	SEC CONFISCION	
3.5	Confirm working hours. Hours	08:00- Mon-		(1) (1)	
4	Project Site Meetings			100 mg/s	
4.1.	Confirm accommodation for site meetings:- EDCS office (provisional due to Covid 19). progress meetings to be agreed.	. Final c	letails for futu	re	
4.2.	Site meetings will be chaired by the Project Administrator who will take the minutes. The to record progress, problems arising on site etc., and to carry out Contractor Appraisals		tings' purpose	will be	
	Intervals of meetings Meetings to be held within overall room	of progn	ess meetings.		
4.3	1904-10422/2007/2/0356 Activities and the company of the company o	Date	TB	3	
400 miles		140.00		THE CASE	\$127-2015-0-FA
15 M	<u>Project Communications</u>				
5.1	Confirm if site telephone is required. Site No		enganosa karen		
5.2	Confirm addresses for communications and number of copies required.		Number	TBA	
	Address:- Correspondence by e-mail where possible. If required, mail to be sent to EDC Dundee, DD3 8PL.	CS, 35	3 Clepington	Road,	
6	Quality Control				
6.1.	Contractor and COW checks to ensure quality control.				
7	Health and Safety				體設計
7.1.	Has Contractor developed & passed H & S Plan to Planning Supervisor. If no give action required confirmed that the Construction Phase Health and Safet been sent to the for comment confirmed that the works could not start on site until			cts had	
	It is emphasised that no work is to commence on site until the Client has deemed Developed Health and Safety Plan suitable.	d the F	rincipal Con	tractor's	

7.2.	Hot Work Permit System to apply for any hot work. Ask for example of Contractor's Hot Work If there is not one give Contractor a copy of the DCC permit. confirmed any hot works would be in accordance with DCC hot works policy.	Permit.		
7.3.	Health and Safety matters will be monitored at each site meeting.			
7.4	Has Contractor made contact with the CDMC Has the info for the Health & Safety File been passed to the CDMC If no give action required:-	YES YES	NO ON	
7.5	Has the contractor sent a copy of the F10 to DCC's Corporate H&S team. If F10s are applicable to send a copy to	YES	NO	
8	Contractors Matters			
8.1.	Has the contractors issued a programme at the meeting. If no give action required:- to e-mail a copy of the programme for both projects.	YES	NO	
9	Quantity Surveyor's Matters		Sea Se	
9.1	advised that a valuation had already been submitted by	orage of materi	als.	
10	Consultants Matters (Architects, Mechanical, Electrical, Structural, Ot	her)		
10.1	advised that the intention would be to remove all chimneys where not in use to ask whether chimneys are lived to check with Structural Engineers whether there are any issue removals.	to chec s with chimney		
10.2	confirmed that bat surveys had been undertaken for both projects and that no bats had been a copy of the reports onto the contractor.	en found. to	forward	
10.3	confirmed that the extent of fire proofing works was to be agreed on site once the roof was	opened up.		
10.4	confirmed the new roof tiles were similar to the existing and therefore no structural assess would be required.	ment for loadin	gs	
10.5	It was agreed that all expansion pipes and overflow pipes were to be removed if redundant.			
10.6	confirmed that he would appreciate the contractors input where it was felt any details show could be undertaken in a more practical way to advise the feels any of the details we construct in a different way.			
10.7	confirmed the roof tile fixing specification was to be obtained from the roof tile manufacture provide the fixing specification. confirmed the roof tiles were Russell Double Roman tiles.	was aske	ed to	
10.8	confirmed he would require confirmation of the specification of all other roof components to be obtained and passed to for inspections.	o allow fixing de	etails to	
10.9	confirmed a Building Warrant application had been made for the projects and that he was	awaiting appro	val.	
11	Client			
11.1	No client matters.			
12	Clerk of Works Matters			
12.1	No Clerk of Works matters.			a III Caracia and Caracia
13	Any Other Business			
13.1	None	7	TO THE STATE OF	



PROOF 6: TILE FIXING SPECIFICATION

Site details:

Reference:

210730151151ASR

Date:

30/07/21

Client: Project: **Dundee City Council** 19-514 - St Marys 10th Dev Ph.3 - Roof Replacement

Plots:

St Ninian's Terrace 7, 27, 29, 51, 59-63 St Giles Terrace 68, 72, 86-88, 94

St Filans Terrace 20, 22

Location:

St. Giles Terrace, Dundee

Postcode:

DD3 9JG

Wind calculation parameters (using BREVe defaults):

Altitude:

142.0m [max within 500m]

Terrain: Heights Hr, He: Site is in mixed terrain - Town, Country

8.0 m, 6.0m

Close to airport?

No

Vmap (BSEN1991-1-4):

25.1 m/s

Design gust speed/pressure:

43.2 m/s ; 1146.4 N/m2

Roof parameters:

Tile type:

Double Roman

Ridge tile, type:

Half Round Ridge, gap in underlay at ridge

Verge type:

Dry Fix - Dry Verge

Roof type, pitch, substrate:

Duopitch, 35°, Non permeable underlay or sheet sarking

Ridge height:

8 m

Batten type: Counterbattens: Class 1 timber (C16/18/22) Yes, Depth= 19.0 mm

Ceiling type:

Ceiling, not well sealed 75 mm

Headlap:

Building length, width (L, W):

25 m, 8 m

Recommended fixing specification:

Note: When using dry verge the dry verge system counts as one of the TWO perimeter fixings.

General areas:

Two smooth nails per tile, length 40 mm, diameter 3.35 mm

Local areas: Perimeter tiles: Clip plus one smooth nall per tile, length 40 mm, diameter 3.35 mm Clip plus one smooth nail per tile, length 40 mm, diameter 3.35 mm

Eaves tiles: Verge tiles: Clip plus one smooth nall per tile, length 40 mm, diameter 3.35 mm Russell Roof Tiles Dry Verge with specified fixings

Ridge:

Use Russell Roof Tiles Dry Ridge System with specified fixings

Local area definition:

5 course(s) of tiles up/down from the ridge/eaves/edge/abutment/obstruction

3 course(s) of tiles in from the verge/side/abutment/obstruction


Underlay:

1,032 N/m² when tested in accordance with BS5534 Annex A

(minimum uplift resistance)


Disclaimer: This fixing advice is based on information supplied by the customer. It is the customer's responsibility to ensure that the information given is correct and that all relevant details that may affect the site wind speed have been identified. The calculations use the methods of BS5534:2014 and BS8612 are only valid for use with the Russell Roof Tiles products shown.

Russell Roof Tiles, Nicolson Way, Wellington Road, Burton-on-Trent, Staffordshire, DE14 2AW Tel: 01283 517070 Fax: -01283 516290 Web: www.russellrooftiles.co.uk



BILL OF QUANTITIES

et 11:25 am, Aug 65, 2020



BILL OF QUANTITIES

RECEIVED

By at 11:41 am, Aug 03, 2020

Revision		Description		Checked	0	ste .
	Project Title	Proposed Roofing St Marys 10th Deve			File Ref. 19-514 OCC ID	
Dundee City Council	Orawing Title	Cloaked Verge Det	ail		Drwg No. 402	
Design & Property Division	Drawn	Checked	Scale 1:10 @ A3		Date Mar 20	Rev. TO

-All timber to be from the following source, in order of preference (1) Recycled wood and (2) FSC, PEFC, CSA, SFI certified as approved by DEFRA. The Council will not accept timber which has been illegally logged.
-Reproduction by permission of Ordnance Survey on behalf of HMSO, © Crown Copyright and Database Right 2018, All rights reserved. Ordnance Survey Licence No. 100023371
-All specifications to be read as "EQUAL AND APPROVED"


Proprietary in-line tile vents to be installed as close to eaves as possible. Spacings shown are indicative only. Actual spacing of units is to be as appropriate to provide the

correct levels of ventilation. Lines of Rear of Building Bonding gutter flashing at Eaves height separating approx 5100mm junctions between new walls. All existing gutters to roofs being SVP RWP from FFL and retained roofs. replaced to be carefully removed and disposed of. Existing and new gutters to be cap ended where a water tight connection cannot be made. Additional RWPs to be installed where required. -Roof All chimneys to roofs Light Light being renewed to be Rooflights in roofs being renewed Roof | either demolished, or Ventilated to be removed and disposed of. Light Roof Pitches Light refurbished, subject —dry ridge. Approx 32° to confirmation. Detail` 402 Ridge height 00 00 approx 7700mm from FFL All chimneys serving properties being Detail \ / Detail \ / Detail \ re-roofed are to to be either demolished, 406 or refurbished, subject to confirmation. Cloak tiles or dry verge system to be fitted to verges. RWP RWP 6830 Approx 6580 Approx 6580 Approx 6830 Approx Front of Building No 39 St Clement Place No 37 St Clement Place No 35 St Clement Place No 33 St Clement Place Type D Type D Type D Type D Detail (not to be replaced) (not to be replaced) (not to be replaced) NB: Roof shown is the same as the following roof to be replaced: • 27 St Clement Place Roof Plan

All junctions between separating walls and the underside of the roof to roofs being renewed are to be checked on site by the Contract Administrator.

Existing cast iron rain water goods at sections of roofs being renewed are to be replaced with new uPVC sections. Top sections of SVPs to be replaced as required to allow for new roof oconstruction.

All existing fascias to roofs being replaced to be carefully removed and disposed of and replaced with new uPVC. Junctions between retained and new fascias are to be finished with a uPVC junction trim. Existing concrete corbelled soffits to be retained. New section of uPVC soffit to be fitted at end of elevations and to wrap around gables.



SPECIFICATION NOTES

1. EXISTING BUILDING CONSTRUCTION:

@ 1:100

- The walls and chimneys are constructed in concrete blockwork.

 The roof is constructed in a timber structure and is finished with concrete tiles.
- The chimneys are fitted with sectional concrete coping stones and clay pots.

2. PREPARATION:

Carefully remove and dispose of existing tiles, roof vents , battens, and underlay.

Existing roof sheathing to be checked and notice given for any defective boards. Any loose boards to be adjusted to level and securely fixed. Punch in protruding fasteners and plane or sand to achieve an even surface. Moisture content: Not more than 22% at time of covering. Give notice if greater than 16%. If the roof is sheathed with wood fibre board this is to be completely removed and disposed of. Roof sheathing to be removed as required to allow for any fire proofing improvements. Carefully remove and dispose of all existing roof lights.

Carefully remove and dispose of the existing guttering, and fascias. Carefully remove the existing rainwater pipes. Where required to allow for roofing works, carefully remove and dispose of the SVPs at junction with roof. Extent of SVPs to be replaced to be agreed on site. The Contract Administrator is be notified upon the discovery of any rotten

timbers.

Roof access and site set up are to be agreed with the Principal Designer through the CPH&SP.

The specification is to be read in conjunction with all project issue plans and documents. Any contradiction between the different sources of information provided is to be brought to the attention of the contract administrator.

3. CONSTRUCTION PHASE HEALTH AND SAFETY PLAN (CPH&SP): The contractor is to submit a construction phase health and safety plan prior to the works being permitted to start on site.

Dundee City Council City Development are to provide a Pre Construction Information Pack (PCIP) along with the tender documents which provides

the key information required for the contractor to compile the CPH&SP.

4. ASBESTOS:

Dundee City Council City Development are to arrange for an asbestos survey to be provided for the areas of the buildings which are affected by the works.

Downtaking works are not permitted to start on site by the contractor until the asbestos survey has been received. The contractor is to contact the Contract Administrator if they have any asbestos related concerns in relation to the building.

5. ROOF SHEATHING/ SARKING:

Where sheathing boards are to be patched, the replacement sections are to be the same thickness as the existing.

Where the whole roof sheathing is to be replaced the new boards are to be 12mm thick OSB3 roof sheathing boards securely fixed through the roof structure.

6. UNDERLAY:

New underlay is to be a high resistance non-breathable membrane in accordance with BS 5534 Part 1 and is to be installed in accordance with

manufacturers written instructions.
Underlay to be laid parallel to eaves, maintaining consistent tautness with vertical laps not less than 100mm wide (or width as recommended by the manufacturer), covered with tile counter battens supports or sealed using proprietary sealant as recommended by the underlay manufacturer.
Horizontal laps of 150mm specified.

Underlay to be lapped with exposed eaves skirt to provide fully weathertight finish.

Underlay to be handled carefully to prevent tears and punctures. Penetrations: Use proprietary underlay seals or cut underlay to give a watertight fit around pipes and components. Where pipes and other components penetrate the underlay, cut neatly and accurately and turn flanges up to give a tight, watershedding fit.

Ventilation paths not to be obstructed.

Note: If tear occurs repair with adhesive tape, or cut new section of underlay, remove torn section by cutting close to sides of rafters, slide up new section of underlay, staple sides to rafters.

7. NEW ROOF TILES:

New roof tiles are to be concrete single lapped interlocking Double Roman roof tiles with a smooth finish.

All roof tiles are to be mechanically fixed in accordance with the manufacturers instructions and in accordance with the latest edition of BS

The contractor is to contact the roof tile manufacturer to obtain a site specific fixing specification. The contractor is not to use historic experience as a basis for the fixing specification.

All head lap distances are to be be in accordance with the manufacturers written instructions and based on the pitch of the roof.

The contractor is to notify the Contract Administrator if the roof pitch is less than anticipated and too shallow a pitch for the roof tile.

8. ROOF RIDGE:

The ridge is to be a proprietary mechanically fixed ridge ventilation system providing a continuous weathertight air path from the roof void to the outside. The system is to provide ventilation to BS 5250:2011 and to comply with BS 5534:2014 for mechanical fixing.

The ridge tiles are to be half round, and in a colour, material, and finish to match the roof tiles.

The tiles are to be fixed with proprietary clips and fixings to provide approved installation in accordance with manufacturers requirements

9. VERG

The verge of the roof is to be finished with Double Roman cloak verge tiles. The tiles are to be concrete in a colour and finish to match the roof

An undercloak is required to be installed between the battens and structure, touching the inside face of the tile to prevent bird ingress. The verge tiles are to be secret fixed.

The components that make up the Cloaked Verge System must comply with BS EN 490: 2011, BS EN 1304: 2013 and the latest revision of BS 5534. The cloak tiles are to be compatible with the roof tiles and are to be installed in accordance with the manufacturers instructions and in accordance with the latest edition of BS 5534. The verge overhang is to be the same width at both sides.

The verge overhang is to be the same width at both sides

10. EAVES:

Rafter trays are to be installed over the rafters to ensure a continuous 50mm free air path is provided through to the the roof ridge.

A proprietary black PVCu rigid eaves support tray is to be fitted at the eaves. The eaves support tray is to be lapped a minimum 150mm. A timber tilting fillet is required below the support tray if the roof pitch is below 20°.

The roof underlay is to overlap the eaves skirt.

11. CAVITY CLOSERS:

Where the wall heads are not currently closed they are to be fitted with a cavity closer. New cavity closers are to be manufactured from rock mineral wool with a non-combustible classification, and is to be enveloped with a polythene sheet.

The cavity closer is to be tightly friction fitted at the wall head to close the

gap.

The cavity closer is to have a 60 minute fire integrity rating.

12. FIRE STOPPING:

Additional fire stopping is to be undertaken to the existing separating walls only when instructed by the Contract Administrator following a site assessment. The Contractor is to notify the Contract Administrator when the roof is ready to assess any fire stopping requirements.

Where fire stopping is required: Fill space over top of wall with layers of rock mineral quilt with a non-combustible classification so that it is tightly compressed between the wall head and underside of the rigid sarking/sheathing board. Tuck edges of quilt between edges of wall and adjoining rafters.

Between the roof tiles and sarking/sheathing, lay 300mm wide pads of mineral fibre quilt thick enough to seal all gaps and cut to fit snugly between the battens and counter battens. Fix in position with continuous self adhesive tape from ridge to eaves before installing the tiles. At boxed eaves completely seal air paths in the plane of the separating wall with wire reinforced rock mineral wool quilt with a non-combustible classification. Rock mineral wool sections are to be one 50mm thick piece nailed to either side of the rafter and carefully cut to shape to provide fire stopping.

13. ROOF SPACE VENTILATION:

Eaves and ridge ventilation is to be installed to provide ventilation into the roof space complying with the latest edition of BS 5250. At the eaves, proprietary in-line vents are to be installed as close to the eaves as possible to provide the eaves ventilation. In-line vents are to be in a colour and profile to match the roof tiles and are be finished in the same plane as the roof tiles ie- no 'mushroom' type tile vents permitted. 10000mm²/m continuous ventilation is to be provided at the eaves. The ridge ventilation is to be provided by installing a ventilated dry ridge system providing 5000mm²/m continuous ventilation. Ventilation is to be in accordance with BS 5250: 2002 and installed in accordance with manufacturers instructions and in accordance with the latest revision of BS 5544.

14. GUTTERS and RWPs:

New gutters are to be PVCu 110mm x 75mm semi eliptical gutters with high flow capacity. The gutters are to be fixed to the fascias using proprietary PVCu fixing brackets. Gutters are to be kitemarked to BS EN 607 and BS EN 1462. New RWPs are to be circular PVCu i n size to match existing. New pipework is to be kitemarked to BS EN 1329-1. Gutters and pipes are to be kept free of debris and cleaned out at completion. Gutters to be tested for leaks upon completion.

Retained and new gutters are to be cap ended at any junctions between retained and new roofs. New RWPs are required where an outlet has been

15. SVPs:

New sections of uPVC SVPs are to be installed in colour and size to match existing. New pipe work and fittings to be kitemarked to BS EN 1329-1. New pipe work to be bent round the outside of the soffits and fascias. All support brackets are to be uPVC with suitable number of brackets required to provide adequate support for new sections of pipe.

removed from a run due to cap ending gutters.

Colour of gutters and RWPs is to match existing.

16. NEW SOFFITS AND FASCIAS:

NEW SOFFITS AND FASCIAS:

New fascias are to be formed with cellular PVCu. All extruded cellural PVCu profiles are to be manufactured in accordance with BS 7619:2009. The boards are to be of a suitable depth for the application. The fascia boards are to be approx 16mm.

The boards are to be jointed using proprietary panel joints. Joints locations are to be agreed on site.

The fascias are to be mechanically fixed in accordance with the manufacturers instructions. All fixings are to be A4 marine grade and comply with BS EN ISO 3506: 1+2, or austentitic stainless steel grade 316. Any exposed fixing heads are to be plastic coated in a colour to match the boards. All fixings are to be evenly spaced.

The new fascias are to be installed in accordance with the 'British Plastic.'

The new fascias are to be installed in accordance with the 'British Plastics Federation Code of Practice For The Installation of Cellular PVC-U (PVC-UE) Roofline Systems'

Where a junction is required between retained and new fascias, the existing material is to be carefully cut at the required junction location and the junction finished with a uPVC junction trim. The fascia colour is to be black or anthracite grey- the final colour is to be confirmed. The new fascias are to have a hockey stick type return at the bottom edge to mask the edge of the existing concrete soffit.

The existing sectional concrete soffits/ wall heads are to be be retained.

17. TIMBER

All timber must be obtained from fully verifiable Forest Stewardship Council FSC or Pan European Forest Certification PEFC. Any timber used for support work or battening is to be of sound quality and preservative treated in accordance with BS 8417. All timber used for closing openings is to be structural grade C16. Counter battens are to be 50 x 25mm timber sections. Counter battens are to be securely fixed through the rafters.

Tile battens are to be 38 x 25mm timber sections for 450mm rafter centres, and 50 x 25mm timber for 600mm centres.

Battens should span at least three rafters and be at least 1.2m long. No more than one in four battens should be joined over one truss for gauges over 200mm. For gauges less than 200mm there can be a maximum of three consecutive joins in any twelve battens.

Fixings to be suitable for the wind load resistance as set out in BS 5534 Annex H7.

 100×50 mm (Nom) timber sections are to be used to close off the roof light openings.

18. LEAD FLASHINGS:

All lead works to be in accordance with BS 6915 and latest edition of 'Rolled lead sheet. The complete manual' published by the Lead Sheet Association. All lead installers to be trained in the application of lead coverings/ flashings and to submit records of experience on request. Flashings to be pre-formed by measuring, marking, cutting and forming prior to assembly wherever possible. Marking out not be carried out using scribers or other sharp instruments without approval. Bossing and forming to provide straight and regular bends, leaving sheets free from ripples, kinks, buckling and cracks.

Finished work to be fully supported, adequately fixed to resist wind uplift but also able to accommodate thermal movement without distortion or stress. Finished work to be protected to prevent staining, discolouration, and damage by subsequent works.

Building paper is to be fitted below all new lead work.

All lead is to be treated with patination oil. Patination oil to be applied to ALL new lead work. Patination oil is to be applied as soon as practical, apply a smear coating to lead, evenly in one direction and in dry conditions.

19. BONDING GUTTER:

Junctions between retained and new roofs are to be weathered using a proprietary dry fix bonding gutter.

Edges of existing roof sheathing to retained roofs to be neatly cut to allow

Edges of existing roof sheathing to retained roofs to be neatly cut to a for installation of new bonding gutter detail.

Gutter to be manufactured from GRP and to be BS 5534 compliant.

Central upstand height of gutter to suit roof tile type.

Bonding gutter to be positioned allow the roof tile bond to be maintained and using a tile and a half as required.

Bonding gutter to overhang 50mm in to rain water gutter. Joints in

bonding gutter are to be lapped a minimum length in accordance with the manufacturers recommendations. When mechanically fixing the slates or tiles to the side of the bonding gutter care should be taken not to make any punctures to or between the water channels.

A code 4 lead saddle is to be fitted over the bonding gutter ridge joint in accordance with the latest edition of BS 6915.

20. CHIMNEYS REMOVAL (Subject to Confirmation):

The client is to check with all tenants whether the the chimneys are operational and advise whether the chimneys are to be removed.

If confirmation is received, the chimneys are to be carefully taken down along with any copes, chimney, pots, lead flashings, etc.

All demolition works are to be undertaken in accordance with BS 6187.

Contractor to provide full Risk Assessments and Method Statements to the Principal Designer for approval prior to the start of any demolition

21. CHIMNEY REFURBISHMENT (Where Full Removal is Not Required):
The chimney copes are to be re-pointed as required. If any copes are damaged beyond repair, the contractor is to notify the Contract Adminstrator to allow an inspection to be made.
All chimney pots are to be checked for stability. Any loose haunching is to be removed and any loose chimney pots re-haunched to secure.
All boss render is to be carefully removed from the chimneys. All areas where the render has been removed are to be patched with undercoat render to bring level. All existing lead flashings are to be removed and new lead flashings installed. A bell cast bead is to be tied in with the lead chimney flashings, and stainless steel expanded metal lath is to be mechanically fixed over the existing render before a two layer dry dash render is applied over the whole chimney.

22. TV AERIALS & SATELLITE DISHES:

Aerials and satellite dishes are to be checked for operation. Any redundant aerials are to be permanently removed subject to confirmation from the Contract Administrator.

Any aerials and satellite dishes which are to be retained are to be temporarily removed and fitted to the scaffolding by a qualified aerial contractor. Residents are to be consulted throughout this process to ensure that a good reception is retained at all times. At the completion of the works when any aerials and satellite dishes are re-positioned to their permanent location the residents are again required to be consulted to ensure a good reception is received.

All fixing brackets, and LNB connections, are to be renewed as required re-fixing the dishes and aerials.

23. COLD WATER STORAGE TANKS:

Check existing cold water storage tank in roof space and report findings/defects.

Extend overflow pipe from cold water storage tank as required.

4. SILICONE SEALAN

Silicone sealant to be low modulus type to BS 5889 type A gun applied

25. DISCHARGE PIPE TERMINATIONS AND OVERFLOW PIPES: Any overflow or discharge pipes are to be checked for operation. Any redundant pipes are to be permanently removed.

26. WASTE MANAGEMENT: The contractor must adopt a waste management system. Waste management is to be carried out on or off site and must be confirmed within the CPH&SP.

General:

All elements of the roof are to be fully installed in accordance with the manufacturers written instructions.

All workmanship standards to be in accordance with BS 8000-6.

All roof tiling and slating to be installed in accordance with the latest revision of BS 5534

All roof to be fully cleaned before the removal of the scaffolding. All windows, including cills/frames etc, are to be fully cleaned as the scaffolding is being removed. The contract administrator is to be given notification for inspection prior to the scaffolding being removed.

Any defects in relation to any part of the building services terminations noticed by the contractor are to be brought to the attention of the Contract Administrator.


Contractor to ensure all roofs are watertight at the end of each working day. The contractor will be held responsible for any water ingress into the building as a result of the ongoing works.

All areas are to be fully cleared of any materials and equipment prior to

Revision Description SVPs confirmed to be replaced at junction with roof only. 17/10/20 File Ref. Proposed Roofing Works 19-514 St Marys 10th Development Phase 3 DCC ID City Council Roof Plan & Specification Drwg No. Buildings B City Development Design & Property Division [1:100 @ A1 Mar 20


City Development, Dundee House, 50 North Lindsay Street, Dundee, DD11LS Tel: 01382 434000

-All timber to be from the following source, in order of preference (1) Recycled wood and (2) FSC, PEFC, CSA, SFI certified as approved by DEFRA. The Council will not accept timber which has been illegally logged.
-Reproduction by permission of Ordnance Survey on behalf of HMSO, © Crown Copyright and Database Right 2018.
All rights reserved. Ordnance Survey Licence No. 100023371



Front Roof Elevation

@ 1:100



No 95 St

Type A


Kilda Road

Rear Roof Elevation @ 1:100


No 93 St

Type A


Kilda Road



Front Right Elevation 93 St Kilda Road Type A



Front Roof Elevation @ 1:100




Rear Roof Elevation @ 1:100

BILL OF QUANTITIES

Checked Project Title Proposed Roofing Works
St Marys 10th Development Phase 3 File Ref. 19-514 Dundee DCC ID City Council Elevations Drwg No. Building Type A 202 City Development Design & Property Division Date 1:100 @ A1 Mar 20 City Development, Dundee House, 50 North Lindsay Street, Dundee, DD11LS Tel: 01382 434000

NB: Refer to location plan for roofs to be

replaced.




BILL OF QUANTITIES

with the plans and specification notes

RECEIVED et 11:40 am, Aug 05, 2020

Revision	Description			Description Checker		Checked	hecked Date	
Dundee City Council	St N	posed Roofing Jarys 10th Dev	Works elopment Phase 3		File Ref. 19-514 DCC ID			
City Council City Development	Orawing Title Eav	es Detail			Drwg No. 401			
Design & Property Division	Drawn	Checked	Scale		Date	Rev.		
			1:10 @ A3		Mar 20	TO		

-All timber to be from the following source, in order of preference (1) Recycled wood and (2) FSC, PEFC, CSA, SFI certified as approved by DEFRA. The Council will not accept timber which has been illegally logged. -Reproduction by permission of Ordnance Survey on behalf of HMSO, © Crown Copyright and Database Right 2018. All rights reserved. Ordnance Survey Licence No. 100023371 -All specifications to be read as "EQUAL AND APPROVED"




BILL OF QUANTITIES



Revision	Des	cription		Checked	D:	rie
Dundee	St Ma	osed Roofing arys 10th Dev	Works elopment Phase 3		File Ref. 19-514 DCC ID	
City Council City Development	Drawing Title Sepa	rating Wall/ R	oof Junction Detail		Drwg No. 403	
Design & Property Division	Drawn	Checked	Scale 1:10 @ A3		Date Mar 20	Rev.

⁻All timber to be from the following source, in order of preference (1) Recycled wood and (2) FSC, PEFC, CSA, SFI certified as approved by DEFRA. The Council will not accept timber which has been iflegally logged.
-Reproduction by permission of Ordnance Survey on behalf of HMSO, © Crown Copyright and Database Right 2018.
-All rights reserved, Ordnance Survey Licence No. 100023371
-All specifications to be read as "EQUAL AND APPROVED"



19-514

DCC ID

404

Date

Rev.

TO

St Marys 10th Development Phase 3

Scale

1:10 @ A3

Ridge Detail


Checked

City Development, Dundee House, 50 North Lindsay Street, Dundee, DD11LS Tel: 01382 434000

City Development
Design & Property Division Drawn

⁻All timber to be from the following source, in order of preference (1) Recycled wood and (2) FSC, PEFC, CSA, SFI certified as approved by DEFRA. The Council will not accept timber which has been illegally logged.
-Reproduction by permission of Ordnance Survey on behalf of HMSO, © Crown Copyright and Database Right 2018.
All rights reserved, Ordnance Survey Licence No. 100023371

⁻All specifications to be read as "EQUAL AND APPROVED"



BILL OF QUANTITIES

RECEIVED
By 11:44 am, Aug 05, 2020


Revision	Descri	noite		Checked	D	ste
	I I I I I I I I I I I I I I I I I I I				File Ref. 19-514	
Dunc	Council Drawing	-1.154 -			DCC ID	
City Develop		y Capping D	et ail		Drwg No. 405	
Design & Proper	ty Division Drawn I	Checked	Scale 1:20 @ A3		Date Mar 20	Rev.

-All timber to be from the following source, in order of preference (1) Recycled wood and (2) FSC, PEFC, CSA, SFI certified as approved by DEFRA. The Council will not accept timber which has been illegally logged.

-Reproduction by permission of Ordnance Survey on behalf of HMSO, © Crown Copyright and Database Right 2018.

All rights reserved. Ordnance Survey Licence No. 100023371

⁻All specifications to be read as "EQUAL AND APPROVED"



-All timber to be from the following source, in order of preference (1) Recycled wood and (2) FSC, PEFC, CSA, SFI certified as approved by DEFRA. The Council will not accept timber which has been illegally logged.
-Reproduction by permission of Ordnance Survey on behalf of HMSO, © Crown Copyright and Database Right 2018, All rights reserved. Ordnance Survey Licence No. 100023371
-All specifications to be read as "EQUAL AND APPROVED"

NB: Final confirmation is required by the Contract Administrator to establish whether the existing chimneys are to be refurbished.

NB: Existing chimney shown is indicative only. Actual chimneys on site will vary but the proposed details remain the same. For actual indicative size of chimneys see plans.

NB: All detail drawings are to be read in conjunction with the plans and specification notes.

Lead cover flashing over lined back box gutter.

Roof membrane lapped over back of lead flashing.

Continuous arris rail/ tilting fillet along upper edge of gutter.


Building paper required below all new lead work.

Back gutter formed in support timber and lined in 12mm marine grade plywood and lined in code 5 lead.

BILL OF QUANTITIES



Revision	Description Checked			Date		
Dindo	Project Title	Proposed Roofing St Marys 10th Devi			File Ref. 19-514	
Dundee City Council	Drawing Title	Chimney Refurbishment Detail Front and Back			Drwg No. 406	
Design & Property Division	Drawn	Checked	Scale 1:10 @ A3		Date Mar 20	Rev.



	City Council	Drawing Title Chimn	nev Refurbishm	ant Datell	1
		Sides	iey Kelulbishin	eni Detan	Drwg No.
	City Development				407
-All timber to be from the following source, in order of preference (1) Recycled wood and (2) FSC, PEFC, CSA,	Design & Property Division	Drawn	Checked	Scale	Date
SFI certified as approved by DEFRA. The Council will not accept timber which has been illegally logged.				1:10 @ A3	Mar 20
-Reproduction by permission of Ordnance Survey on behalf of HMSO © Crown Copyright and Database Right 2018.					

All rights reserved, Ordnance Survey Licence No. 100023371 -All specifications to be read as "EQUAL AND APPROVED"

19-514


DCC ID

Rev.

ТО

St Marys 10th Development Phase 3

City Development, Dundee House, 50 North Lindsay Street, Dundee, DD11LS Tel: 01382 434000



RECEIVED

at 11:46 am; Aug 05, 2020

Rt		Description		Checked	D	ate
Dundee City Council					File Ref. 19-514	
		metric Chimney	Flashing Detail		Drwg No. 408	
Division	Drawn	Checked	Scale 1:10 @ A3	<u> </u>	Date Mar 20	Rev. T0
	ent	Project Pfu Title St Drawing Title Iso	Title St Marys 10th Dev Communication of the St Marys 10th Dev Drawing Title Isometric Chimney ent	Project Title Proposed Roofing Works St Marys 10th Development Phase 3 Drawing Title Isometric Chimney Flashing Detail ent Division Drawn Checked Scale	Project Title St Marys 10th Development Phase 3 Drawing Title Isometric Chimney Flashing Detail ent Division Drawn Checked Scale	Project Title St Marys 10th Development Phase 3 19-514 OCC ID Drawing Title Isometric Chimney Flashing Detail Drwg No. 408 Drawn Checked Scale Date

-All timber to be from the following source, in order of preference (1) Recycled wood and (2) FSC, PEFC, CSA, SFI certified as approved by DEFRA. The Council will not accept timber which has been illegally logged.
-Reproduction by permission of Ordnance Survey on behalf of HMSO, © Crown Copyright and Database Right 2018.
All rights reserved. Ordnance Survey Licence No. 100023371
-All specifications to be read as "EQUAL AND APPROVED"

F 022 CLERK OF WORKS WEEKLY REPORT

Client Ref	社論的	TARRES		Š.							3	
To b	e comp	leted b	y lead Co	OW's]		100	2350	To be	completed by	all COV	N's
Au Sessio vi	CHAPTE .	3 4523	E WELLEY	SEE I	(GENERA				10		
West State Land	W. Carl	PERS	ONNEL	589SH 00	C			rt Number	3	NO.	1262	194209
Supervising Office		EDCS		Davit .			Wee	k Ending	73	03/12/	2021	1110
Contractor	UNITED S	如人物		Contrac	t Start Date	50	15/11/		SNAME			
Clerk of Works	900				The Follow			Comp. Date	S	06/05/		No.
Site Supervisor	SEAGUE	NACHORISES	A 400 T 4 7 1			Marin A	Predicted Comp. Date			T,B.C		
Site Phone No		THE STATE OF			185 95	Part of the second		Against Prog		none to	report	
C= MucS()	100	STATE OF	ensekur.	Strift 2350)	为主体数		Emergen	cy Phone No	90		MARK!	
	77 1 2 2 2 2		s X ^a riiles			THER RE	PORT	8 LIT	Jo		1 (7)	J- 16
	Day	100			М	.C		PM		.c	Hour	s Lost
	Monday			6017 HRS. 5164	RY			DRY	製物			
	uesday ednesda			the Control of the Control	RY		352 5	DBY		190	1,000	10:10
	eunesua hursday		111111111111111111111111111111111111111	CORNER DE CONTRACTOR	WERS RY	1		SHOWERS			(2)	
10 5	Friday	-	-	Charles Control of	AIN	1		DRY				
5	aturday				SUN.		200	MALIN	(#) (B) (#) (B)			
	Sunday	5							(0) 110 (0) 70			
OF THE WAY IN	771-		7110	Total Ho	urs Los	t (in week)	300 C 100 C	A TOTAL POTOS	101		NOT (SIVEN
IN MERCHANICAL	WE VILL	J. Aug	STREET,			t (to date)					NOT	
The state of the s		-				ORMAT	ON					-36-14
Drawings :	and info	requir	ed	NONE	0.000000	ORMAI	TON .	netra demonêre, v	14023	Monte with a set of	ALTERNATION	Avenue rose
C 4 17 17 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	e write r	-		14004 (600)	SEGERATES	Mary Control	vicinal response	EARLY VALUE	\$1650			727
Attachm				NONE	13. 510,71		list amicor	restrantos en la composita de la composita de La composita de la composita d	Stall		AND STREET	
	e write r	White SHAIR		751	1,7230			4-19-35	OF STATE			A PRESENT
Difficulties (inc	luding s	hortage	s which	NONE F	RECOR	DED	- Table 19	1.00 to 10	4 miles		1 m	010401
may cause de	lays and	action	taken)	SSERECT	15 X	Strake	THE REAL PROPERTY.	PROPERTY OF	156	X 255 1 7 1 1 1	# 1 × 1 × 1	2230
Digital	Photo F	ecord	A W	CONTR	ACTOR	HAS ON F	ILE NAME IN	CATTLEFE	2	是在自己的是代表的	被数据	2,000
		2001	O.W	和建设室/			WATER PARTY	No. of the last of		the scale and less	689430	HARLY.
	/isitors			NONE !	RECOR	DED	2000	游鸟脸,我的		数多位 达尔斯图	201-70¢	性轉音號
	TPRANS.			Same.	200	NAME OF THE PARTY	Marie Control		100	SOUTH THE	AND IN	Mark !
- 07H46 1	F6755	HINA		AMMUS	RY OF	WORK	N PROC	RESS	General General		· -	
	WEV	%	1180	10/1/2	%			%			W .	%
Preliminaries	E34#	1000	785	Roofing		Down Ta		300	G	as Mains		10000
Excavations	Williams)	1		rection	凝煌	Floor Cov		65.5	9534	ectric Mains		
Concrete Foundat	ions		-	Frame		Floor Scr			200	ater Mains		
Piling Foundations		4		1 st Fix	1000	The same of the sa	plication	200	CON.	elecom Mains		
				2 nd Fix	7	Lifts	8	988	100	ternal Works		100
Asphalt Tanking Asphalt Roofing				w Fixing	TOTAL SECTION AND ADDRESS OF THE PARTY OF TH		-	1000		ectrical 1st Fix		75.50
Brickwork/Block E	vternal		Glazing Plaster		(0) (0) (0) (0) (0) (0) (0) (0) (0) (0)	10		新花工		ectrical 2 nd Fix		
Brickwork/Block Ir			Metalw		2000年の	\$7 	-	100000		eating 1 st Fix		1
Drainage	itarries	-	Decora		2000 P000		- 10700	Sec. 200		eating 2 nd Fix		
Paving and Floorie	na	GREEN		grid/tiles	STOLEN	ER.	_	79976		entilation 1 st Fix entilation 2 nd Fix	-	
Masonry	CPA DES	District of the control of the contr	Roof Structure Water 1st Fix						_			
Slater and Tiler	-		_	Roof Covering Water 1 th Fix								
Suspended Floor	USHE	200	Claddir			2		5,000		efects / Handove	er .	
Concrete Structur	е		Rende		15100		-		1000	ommissioning		
Control of the Contro	AMV IA	ICIDE	NTC C	NTDA	DV TC	COODI	JE AL TU	AND CAE		PRACTICE		Contractive.
NONE RECORDS	D		HI3 C	JITTA	MODERN SALES	GOODI	TEALIN	AND SAF	895.55	PRACTICE	tes lendered live live live	
		10000							ACT AND			AMESICAL AND
				THE RESERVE OF THE PARTY OF THE		THE RESERVE OF THE PARTY OF THE	THE RESERVE OF THE PARTY OF	STATE OF THE PARTY OF THE PARTY.	A-WOLDOW	THE RESERVE OF THE PARTY OF THE		ACTES SANCED IN
	A POST		175	1.00			The second	T. C. State of Street, Str.			357	

1
Mark Co.

	THIS WEEKS PROGRESS SUMMARY
Date	Report
	SCAFFOLD ERECTION IN PROGRESS
+2+2	
et unitalis	
Responsible.	
4000000	
gramma artikara 100 Partikara	
April 18	
44.45	
JETO WALL	
19 (E. 27) (A 25)	
Selfer to the self and	
1501 S211-52	
A. 456 S. D.	
ALTON M	
-59/42, FF/8	
	and the state of t
CHARGE CONTR	
4101 MARKET AND AND	
	A SECTION OF A MEAN THE SECTION OF T
是到数件系	
11867/2	
一种基础	
Wester.	
1. 计编程	
100/100	
	The second secon







Request for Information:

RFI: Rolling sheet.

Contract: St Mary's 10th Phase 3

Contract Number 1030/113

To:From:-

Date Requested	Q	uestion :	Date Required	Answer:	Response Issued
29/10/21	1	Protec A1 under tile felt to be used	ASAP	This is OK	
29/10/21	2	Double Roman Red tiles to be used	ASAP	This is Ok	
29/10/21	3	Cloak Verge preferred but dry verge can be used	ASAP	AI no 03 has been issued to confirm that plastic verges are to be used.	
29/10/21	4	UPVC Facia/soffit to be BLACK/GREY in colour (usually white) OR is this now deleted	ASAP	AI no 03 confirms fascias to be white.	
29/10/21	5	Are existing roofs celetex or sarking	ASAP	The existing roofs have a timber based 'celetex' type board.	
29/10/21	6	Has Bat survey been carried out if so can you forward this on	ASAP	Bat survey has been provided.	
29/10/21	7	Does nesting bird survey still require to be carried out	ASAP	No bird survey is required as we are out of nesting season. If any birds are under the tiles they will fly away and nest elsewhere.	

19-514 - St Marys 10th Dev Ph.3 - Roof Replacement

Architect's Instruction

Director of City Development Client

Address:

Floor 5, Dundee House, Dundee

Project

Ref: 19-514

Contractor:

EDCS

Certificate No:

01

Address:

353 Clepington Road

Dundee

DD3 8PL

issue Date:

7 June 2021

Contract Dated:

18/11/20

Sheet:

of 1

Under the terms of the above-named Contract, I/we issue the following instructions:

				Office Use:		
001	Carry out works in	accordance with drawings as listed in draw 07/06/21(A). Drawings all as per tender iss	wing	£ omit	Approx Costs £ add	
	updated to constru	sue but				
					J	
				12.		
					==	
To be signed for and						
On behalf of the issue				:		
Named below	Signed	City Architect				
	<u> </u>	Amount of Contract Sum		£		
		± Approximate value of previous Instructions	ŀ	£		
		± Approximate value of this instruction	ŀ	£		
				£	_ .	
Distribution		Approximate adjusted total	L			
Original		Copies to:		DUNDEE CITY CO	DUNCIL	
to:				City Development		
	Contractor	Client		City Architect		
		Quantity Surveyor		Floor 5, Dundee House 50 North Lindsay Stree Dundee DD1 1LS	t	
		Nominated				
		Sub- Clerk of F Contractor Works	File .	Telephone		

Table of Contents

Title		Page
H60	Plain roof tiling	3
H71	Lead sheet coverings/ flashings	7
R10	Rainwater drainage systems	11

H60 Plain roof tiling

To be read with Preliminaries/General conditions.

TYPES OF TILING

125 CONCRETE ROOF TILING WITH COUNTERBATTENS TO EXISTING ROOFS

- Substrate: Timber sarking on rafters at 450 mm centres.
- Pitch: 35°
- Underlay: Reinforced bitumen membrane to BS 8747, type 1F.
 - Recycled content: Contractor's choice.
 - Direction: Parallel to eaves.
 - Head-lap (minimum): 100 mm.
- Counterbattens:
 - Size: 38 x 19 mm.
 - Fixing: 65 x 3.35 mm galvanized annular ring shank nails.
- Battens:
 - Size: 38 x 25 mm.
 - Fixing: 65 x 3.35 mm galvanized annular ring shank nails.
- · Tiles: To BS EN 490, noninterlocking.
 - Manufacturer: www.marleyeternit.co.uk

roofinginfo@marleyeternit.co.uk

T: +44 (0) 1283 722588

F: +44 (0)1283 722219

Lichfield Road, Branston, Burton-on-Trent. DE14 3HD. Product reference: Modern Concrete plain tiles. .

- Pattern: None.
- Colour: Smooth grey,
- Size: 267 mm x 168 mm.
- Recycled content: Contractor's choice.
- Head-lap (minimum): 65 mm.
- Fixing:

Fixing of local areas: Two nails per tile in every course.

Fixing of general areas: Two nails per tile in every fifth course.

Accessories: None.

TILING GENERALLY

210 BASIC WORKMANSHIP

- General: Fix tiling and accessories to make the whole sound and weathertight at earliest opportunity.
- Setting out: To true lines and regular appearance, with neat fit at edges, junctions and features.
- Fixings for tiling accessories: As recommended by tile or accessory manufacturer.
- · Gutters and pipes: Keep free of debris. Clean out at completion.

Page 4 of 13

240A UNDERLAY

- · Laying: Maintain consistent tautness.
- Vertical laps (minimum): 100 mm wide, coinciding with supports and securely fixed.
- Fixing: Galvanized steel, copper or atuminium 20 x 3 mm extra large clout head nails.
- Eaves: Where exposed, underlay must be BS 8747 Annex B, type 1F, or equivalent UV durable type.
- Penetrations: Use proprietary underlay seals or cut underlay to give a watertight fit around pipes and components.
- · Ventilation paths: Do not obstruct.

245 BATTENS/ COUNTERBATTENS - TREATED

- Timber: Sawn softwood.
 - Standard: BS 5534, clause 4.12.1.
 - Permissible characteristics and defects: Not to exceed limits in BS 5534, Annex C.
 - Moisture content at time of fixing and covering (maximum): 22%.
- Preservative treatment: As section Z12 and Wood Protection Association Commodity Specification C8.
 - Type: Contractor's choice.

255 COUNTERBATTENS ON RIGID SARKING

Fixing: Through rigid sarking into rafters at not more than 300 mm centres.

265 BATTEN FIXING

- Setting out: Align parallel to ridge in straight horizontal lines to gauge of tiles. Align on adjacent areas.
- · Batten length (minimum): Sufficient to span over three supports.
- Joints in length: Square cut. Butt centrally on supports. Joints must not occur more than
 once in any group of four battens on one support.
- · Additional battens: Provide where unsupported laps in underlay occur between battens.
- · Fixing: Each batten to each support. Splay fix at joints in length.

275 TILE FIXING

- · Setting out: Lay tiles to a half lap bond with joints slightly open. Align tails.
- Ends of courses: Use tile and a half tiles to maintain bond and to ensure that cut tiles are as large as possible.
- Top and bottom courses: Use eaves/tops tiles to maintain gauge.
- Perimeter tiles:
 - Verges, abutments and each side of valleys and hips: Twice nail end tile in every course.
 - Eaves and top edges: Twice nail two courses of tiles or clip as appropriate.
- · Fixings for tiles: Nails/clips recommended by tile manufacturer.

280 LOCAL AND GENERAL FIXING AREAS

- Definitions:
 - Local areas: Bands of tiling around all edges or obstructions of each plane of the roof. Calculate extent of each band in accordance with BS 5534, section 5.
 - General areas: Remaining areas of roof tiling.

290 MORTAR BEDDING/ POINTING

- Mortar: As section Z21, 1:3 cement:sand, with plasticizing admixtures permitted.
 - Bond strength providing resistance to uplift: To BS 5534.
- · Weather: Do not use in wet or frosty conditions or when imminent.
- Preparation of tiles and accessories to be bedded: Wet and drain surface water before fixing.
- Appearance: Finish neatly as work proceeds and remove residue.

Page 5 of 13

ROOF TILING EDGES/ JUNCTIONS/ FEATURES

305 GENERALLY

- Fittings and accessories: As recommended by tile manufacturer, do not improvise.
 - Exposed fittings and accessories: To match tile colour and finish.
- Cut tiles: Cut only where necessary, to give straight, clean edges.
- Flashings: Fix with or immediately after tiling. Form neatly.

325 FIRE SEPARATING WALLS

- Separating walls: Completely fill space between top of wall and underside of tiles with mineral wool quilt to provide fire stopping.
- Boxed eaves: Completely seal air paths in plane of separating wall with wire reinforced mineral wool, not less than 50 mm thick, fixed to rafters and carefully cut to shape to provide fire stopping.

525 MITRED HIPS

- Underlay: Lay courses over hip.
 - Overlaps (minimum): 150 mm.
- Mitred tiles: Cut tile and a half tiles and fix to form a straight, close mitred junction.
- Soakers: Interleave with mitred tiles. Fix by turning down over head of mitred tiles.

635 MITRED VALLEYS

- Underlay: Lay strips not less than 600 mm wide centred on valleys. Overlap with general roof underlay.
- Mitred tiles: Cut tile and a half tiles and fix to form a straight, close mitred junction.
- Soakers: Interleave with mitred tiles. Fix by turning down over head of mitred tiles.

660 SIDE ABUTMENTS

- · Underlay: Turn up not less than 100 mm at abutments.
- Abutment tiles: Cut as necessary. Fix close to abutments.
- Soakers: Interleave with abutment tiles. Fix by turning down over head of abutment tiles.

670 TOP EDGE ABUTMENTS

- · Underlay: Turn up not less than 100 mm at abutments.
- Top course tiles: Fix close to abutments.

700 DRY VENTILATED RIDGES

- Underlay: Provide air gap at apex.
- Dry ridge fixing battens: 50X50mm.
- Dry ridge tiles:
 - Manufacturer: www.marleyeternit.co.uk

roofinginfo@marleyeternit.co.uk

T: +44 (0)1283 722588

F: +44 (0)1283 722219

Lichfield Road, Branston, Burton-on-Trent. DE14 3HD. Product reference: DRY RIDGE.

Ridge terminals:

Manufacturer: Not required.
 Product reference: Not required.

Page 6 of 13

VENTILATOR TILES 840

- · Ventilator tiles:
 - Manufacturer: www.hambleside-danelaw.co.uk

marketing@hambleside-danelaw.co.uk

T: +44 (0)1327 701900

F: +44 (0)1327 701909

Long March, Daventry. NN11 4NR or equal and approved by CA. Product reference: HDTV 15/1.

Requirement: To ventilate roof void.

Positions: Eaves, in lowest course clear of insulation.

H71 Lead sheet coverings/ flashings

To be read with Preliminaries/ General conditions.

TYPES OF LEADWORK

200 GUTTER LINING

- Substrate: Existing timber boarding.
 - Preparation: Not required.
- · Underlay: Needle punched nonwoven polyester geotextile.
- Type of lead: Rolled to BS EN 12588.
 - Thickness: 2.00 or 2.24 mm (Code 5).
- · Pretreatment: N/A.
- Joints in direction of fall: N/A.
 - Spacing: N/A,
- Cross joints: TPREN BONDED EXPANSION JOINT.
 - Spacing: 2000 mm.
- Outlets: Turn down 75 mm into fascia gutter.

410 APRON FLASHINGS TO ABUTMENT

- Lead
 - Thickness: 2.00 or 2.24 mm (Code 5).
- Dimensions:
 - Lengths: Not more than 1500 mm.
 - End to end joints: Laps of not less than 100 mm.
 - Upstand: Not less than 75 mm.
 - Cover to abutment: Not less than 150 mm.
- Fixing: Lead wedges into bed joint, clips to bottom edge at laps and 500 mm centres.

430 COVER FLASHINGS TO ABUTMENT FLASHINGS

- Lead;
 - Thickness: 2.00 or 2.24 mm (Code 5).
- · Dimensions:
 - Lengths: Not more than 1500 mm.
 - End to end joints: Laps of not less than 100 mm.
 - Overlap to upstand: Not less than 50 mm.
 - Cover to roof: Not less than 75 mm.
- Fixing: Lead wedges into bed joint, clips to lead upstand at laps and 500 mm centres.

Page 8 of 13

474 CHIMNEY FLASHINGS TO SINGLE LAP TILE ROOFS

- Lead front apron:
 - Thickness: 2.00 or 2.24 mm (Code 5).
 - Dimensions:

Length: Width of chimney plus not less than 150 mm underlap to each side flashing.

Upstand: Not less than 75 mm.

Cover to roof: Not less than 150 mm.

- Fixing: Lead wedges into bed joint.
- Lead side step and cover flashings:
 - Thickness: 2.00 or 2.24 mm (Code 5).
 - Dimensions:

Lengths: Not more than 1500 mm.

End to end joints: Laps of not less than 100 mm.

Upstand: Not less than 65 mm.

Cover to roof: Not less than 150 mm.

- Fixing: Lead wedges at every course and clips (clause 715) at not more than 500 mm centres along free edge.
- Lead back gutter:
 - Thickness: 2.00 or 2.24 mm (Code 5).
 - Dimensions:

Length: Width of chimney plus not less than 100 mm overlap to each side flashing.

Upstand: Not less than 100 mm.

Gutter sole: Not less than 150 mm.

Cover up roof not less than 225 mm.

- Lead back gutter cover flashing:
 - Thickness: 2.00 or 2.24 mm (Code 5).
 - Dimensions:

Length: Width of chimney plus not less than 100 mm overlap to each side flashing.

Cover: Overlap to back gutter upstand of not less than 75 mm.

- Fixing: Lead wedges into bed joint.

GENERAL REQUIREMENTS/ PREPARATORY WORK

510 WORKMANSHIP GENERALLY

 Standard: To BS 6915 and latest edition of 'Rolled lead sheet. The complete manual' published by the Lead Sheet Association.

 Fabrication and fixing: To provide a secure, free draining and completely weathertight installation.

 Operatives: Trained in the application of lead coverings/ flashings. Submit records of experience on request.

Preforming: Measure, mark, cut and form lead prior to assembly wherever possible.

Marking out: With pencil, chalk of crayon. Do no use scribers or other sharp instruments without approval.

 Bossing and forming: Straight and regular bends, leaving sheets free from ripples, kinks, buckling and cracks.

Solder: Use only where specified.

· Sharp metal edges: Fold under or remove as work proceeds.

 Finished work: Fully supported, adequately fixed to resist wind uplift but also able to accommodate thermal movement without distortion or stress.

- Protection: Prevent staining, discolouration and damage by subsequent works.

516 LEADWELDING

 In situ leadwelding: Is permitted, subject to completion of a 'hot work permit' form and compliance with its requirements.

Page 9 of 13

520 LEAD SHEET

- · Production method:
 - Rolled, to BS EN 12588, or
 - Machine cast and BBA certified, or
 - Sand cast, from lead free from bitumen, solder, other impurities, inclusions, laminations, cracks, air, pinholes and blowholes; to code thicknesses but with a tolerance (by weight) of ±10%.
- · Identification: Labelled to show thickness/ code, weight and type.

555 LAYOUT

Setting out of longitudinal and cross joints: Submit proposals.

610 SUITABILITY OF SUBSTRATES

Condition: Dry and free of dust, debris, grease and other deleterious matter.

620 PREPARATION OF EXISTING TIMBER SUBSTRATES

- Remedial work: Adjust boards to level and securely fix. Punch in protruding fasteners and plane or sand to achieve an even surface.
- Defective boards: Give notice.
- Moisture content: Not more than 22% at time of covering. Give notice if greater than 16%.

640 TIMBER FOR USE WITH LEADWORK

- Quality: Planed, free from wane, pitch pockets, decay and insect attack (ambrosia beetle excepted).
- Moisture content: Not more than 22% at time of fixing and covering. Give notice if greater than 16%.
- Preservative treatment: Organic solvent as section Z12 and Wood Protection Association Commodity Specification C8.

645 NEEDLE PUNCHED NONWOVEN POLYESTER GEOTEXTILE UNDERLAY

- Manufacturer: Contractor's choice.
 - Product reference: Submit proposals.
- · Weight: 200 g/m².
- · Recycled content: Contractor's choice.

650 LAYING UNDERLAY

- Handling: Prevent tears and punctures.
- Laying: Butt or overlap jointed onto a dry substrate.
 - Fixing edges: With copper or stainless steel staples or clout nails.
 - Do not lay over roof edges but do turn up at abutments.
 - Wood core rolls: Fixed over underlay.
 - Protection: Keep dry and cover with lead at the earliest opportunity.

FIXING LEAD

705 HEAD FIXING LEAD SHEET

- Top edge: Secured with two rows of fixings, 25 mm and 50 mm from top edge of sheet, at 75 mm centres in each row, evenly spaced and staggered.
- Sheets less than 500 mm deep: May be secured with one row of fixings, 25 mm from top edge of sheet and evenly spaced at 50 mm centres.

- 1 Toler

Page 10 of 13

710 FIXINGS

- Nails to timber substrates: Copper clout nails to BS 1202-2, or stainless steel (austenitic) clout nails to BS 1202-1.
 - Shank type: Annular ringed, helical threaded or serrated.
 - Shank diameter: Not less than 2.65 mm for light duty or 3.35 mm for heavy duty.
 - Length: Not less than 20 mm or equal to substrate thickness.
- Screws to concrete or masonry substrates: Brass or stainless steel to BS 1210, tables 3 or
 - Diameter: Not less than 3.35 mm.
 - Length: Not less than 19 mm.
 - Washers and plastic plugs: Compatible with screws and lead.
- Screws to composite metal decks: Self tapping as recommended by the deck and lead manufacturer/ supplier for clips.

790 SCREW FIXING INTO JOINTS/ CHASES

- Joint/ chase: Rake out to a depth of not less than 25 mm.
- Lead: Dress into joint/ chase and up back face.
 - Fixing: Into back face with stainless steel screws and washers and plastics plugs at not more than 450 mm centres, at every change of direction, and with at least two fixings for each piece of lead.
- · Sealant: Contractor's choice.
 - Application: As section Z22.

JOINTING LEAD

880 WELTED JOINTS

- Joint allowance: 50 mm overlap and 25 mm underlap.
- · Copper or stainless steel clips: Fix to substrate at not more than 450 mm centres.
- · Overlap: Welt around underlap and clips and lightly dress down.

970 PATINATION OIL

- · Manufacturer: Contractor's choice.
 - Product reference: Submit proposals.
- · Location: ALL NEW LEAD.
- Application: As soon as practical, apply a smear coating to lead, evenly in one direction and in dry conditions.

R10 Rainwater drainage systems

To be read with Preliminaries/ General conditions.

GENERAL

110 GRAVITY RAINWATER DRAINAGE SYSTEM

- · Rainwater outlets: Proprietary.
- Gutters: PVC-U.
- Pipework: PVC-U, external.
- Below ground drainage: EXISTING FIRECLAY.
- · Disposal: To surface water drainage.
- Controls: Not applicable.
- Accessories: N/A,

PRODUCTS

350 PVC-U GUTTERS

- Standard: To the relevant parts of BS EN 607 and BS EN 1462, Kitemark certified.
- Manufacturer: www.marley.co.uk

marketing@marleyext.com

T: +44 (0)1622 858888

F: +44 (0)1622 858725

Dickley Lane, Lenham, Maidstone. ME17 2DE.

- Product reference: DEEPFLOW.
- Recycled content: Contractor's choice.
- Profile: PVC-U gutter, HALF ROUND .
- Nominal size: 150 mm.
- Colour: Black.
- Brackets: PVC.
 - Fixings: Stainless steel screws.
 - Size: 50 x 5 mm.
- · Accessories: Gutter stop ends.

FABRICATION

EXECUTION

600 PREPARATION

- Work to be completed before commencing work specified in this section:
 - Below ground drainage. Alternatively, make temporary arrangements for dispersal of rainwater without damage or disfigurement of the building fabric and surroundings.
 - Painting of surfaces which will be concealed or inaccessible.

Page 12 of 13

605 INSTALLATION GENERALLY

- · Electrolytic corrosion: Avoid contact between dissimilar metals where corrosion may occur.
- · Plastics and galvanized steel pipes: Do not bend.
- Allowance for thermal and building movement: Provide and maintain clearance as fixing and jointing proceeds.
- · Protection:
 - Fit purpose made temporary caps to prevent ingress of debris.
 - Fit access covers, cleaning eyes and blanking plates as the work proceeds.

615 SETTING OUT EAVES GUTTERS - TO FALLS

- Setting out: To true line and even gradient to prevent ponding or backfall. Position high
 points of gutters as close as practical to the roof and low points not more than 50 mm
 below the roof.
- · Outlets: Align with connections to below ground drainage.

635 FIXING PIPEWORK

- Pipework: Fix securely, plumb and/ or true to line.
- Branches and low gradient sections: Fix with uniform and adequate falls to drain efficiently.
- · Externally socketed pipes and fittings: Fix with sockets facing upstream.
- Additional supports: Provide as necessary to support junctions and changes in direction.
- · Vertical pipes:
 - Provide a loadbearing support at least at every storey level.
 - Tighten fixings as work proceeds so that every storey is self supporting.
 - Wedge joints in unsealed metal pipes to prevent rattling.
- Wall and floor penetrations: Isolate pipework from structure.
 - Pipe sleeves: As section P31.
 - Masking plates: Fix at penetrations if visible in the finished work.
- Expansion joint pipe sockets: Fix rigidly to buildings. Elsewhere, provide brackets and fixings that allow pipes to slide.

640 FIXING VERTICAL PIPEWORK

- Bracket fixings: Plugged and screwed into masonry.
- Distance between bracket fixing centres (maximum): 1800 mm.

650 JOINTING PIPEWORK AND GUTTERS

- General: Joint with materials and fittings that will make effective and durable connections.
- · Jointing differing pipework and gutter systems: Use adaptors intended for the purpose.
- Cut ends of pipes and gutters: Clean and square. Remove burrs and swarf. Chamfer pipe ends before inserting into ring seal sockets.
- Jointing or mating surfaces: Clean and, where necessary, lubricate immediately before assembly.
- Junctions: Form with fittings intended for the purpose.
- · Jointing material: Strike off flush. Do not allow it to project into bore of pipes and fittings.
- · Surplus flux, solvent jointing materials and cement: Remove.

Page 13 of 13

COMPLETION

TESTING GENERALLY

- TESTING GENERALE.

 Dates for testing: Give notice.
 - Period of notice (minimum): 3 DAYS.
- Preparation:
 - Pipework: Complete, securely fixed, free from defects, obstruction and debris before testing.
- · Testing:
 - Supply clean water, assistance and apparatus.
 - Do not use smoke to trace leaks.
- · Records: Submit a record of tests.

910 GUTTER TEST

- · Preparation: Temporarily block all outlets.
- Testing: Fill gutters to overflow level and after 5 minutes closely inspect for leakage.

920 IMMEDIATELY BEFORE HANDOVER


- Construction rubbish, debris, swarf, temporary caps and fine dust which may enter the rainwater system: Remove. Do not sweep or flush into the rainwater system.
- · Access covers, rodding eyes, outlet gratings and the like: Secure complete with fixings.

APPENDIX 2

Clepington Road Phase 1

Properties Qualifying for Roof Replacement	Page 51
Ground Floor Plan Building Type A 218 and 220 Clepington Road	Page 52
Ground Floor Plan Building Type B and D 212, 214 and 216 Clepington Road	Page 53
Eaves Details	Page 54
Verge Details	Page 55
Chimney Capping Details	Page 56
Soil Vent Pipe Details	Page 57
Separating Wall/Roof Junction	Page 58
Ridge Details	Page 59
Front Chimney Flashing Details	Page 60
Rear Chimney Flashing Details	Page 61
Side Chimney Flashing Details	Page 62
Hip Details	Page 63
Valley Details	Page 64

This page is intentionally left blank






Properties Qualifying for Roof Replacement:

Numbers 212, 214, 216, 218 & 220 (All Council Owned).

Dundaa	Print CLEPINGTON ROAD PHASE 1 RE-ROOFING			ChechediDate File Ref. 18-517	
City Development	Drawing Tide SITE PLANS			Drug. Ho. 101	
City Architects Division	Drawn	Checked	Scale NOTED@A2	Oute AUG 2018	Rev.
oundee House, 50 North L et: 01382 434000	indsay S	itrael, Dundee, DD	1 1LS		

BUILDING TYPE A 218 & 220 CLEPINGTON ROAD




SARKING MADE GOOD 218 220 (DCC) (DCC)

ROOF VENTS TO BE REMOVED AND ROOF VENTS NSVP NISVP N_{DSVP} SVPD SVPN SVPN X SVPN SVPN NOTE: SUB FLOOR VENTS INDICATIVE ONLY TO REAR AND GABLE ELEVATION RWP B

NORTH ELEVATION

SOUTH ELEVATION **37160 APPROX** Detail CAREFULLY REMOVE CAST IRON ROOFLIGHT, INFILL AND CAREFULLY REMOVE CAST 512 IRON ROOFLIGHT, INFILL AND MADE GOOD MADE GOOD CHIMNEY CHIMNEY Detail 506 I C.I. ROOFLIGHT C.I. ROOFLIGHT ASIACROSS | AS ACROSS 000000 00000 /Detail √ 509 CHIMNEY CHIMNEY CHIMNEY TCHIMNEY Detail 507 LADDER Detail 510 CHIMNEY Detail 503 Detail i\ 508 ∕⊠

ROOF PLAN



GROUND FLOOR PLAN (TYPICAL)

EAST ELEVATION

All timber is to be from the following source, in order of preference (1) Recycled wood and (2) FSC, PEFC, CSA, SFI certified as approved by DEFRA. The Council will not accept timber which has been illegally logged Reproduction by permission of Ordnance Survey on behalf of HMSO, © Crown Copyright and Database Right 2011. All rights reserved. Ordnance Survey Licence No. 100023371

New Roof Tiles
Russell 'Galloway' interlocking tiles Colour : Slate Grey Specification: Fully in accordance with manufacturers recommendations.

Ridge
Ventilated dry ridge system with 'Modern' ridge tiles. Colour : To match roof tile Specification: Mechanically fixed with rigid sarking cut back underlay-undertiling felt and sarking boards for unobstructed roof ventilation (min. 5mm gap for roof ventilation). Fully in accordance with manufacturers recommendations. Detail: See dwg. no.18-517/507 for details.

Cloak Verge Dry verge tile Colour: To match roof tile Specification: Fully in accordance with manufacturers recommendations. Detail: See dwg. no.18-517/503 for details.

Specification: Fully in accordance with manufacturers recommendations. Detail: See dwg. no.18-517/502 for details

Existing Expansion Pipes Fit tile colour and profile to match roof tile and extend expansion pipes to suit.

Gable Fascia and Soffit Dry verge tile and new cellular PVC Fascia and ventilated soffit board. Colour: White Specification: Fully in accordance with manufacturers Detail: See dwg. no.18-517/502 for details.

Chimney - Demolition Carefully take down unused existing redundant chimney. Removal to be advised by Client/Architect. Detail: See dwg. no.18-517/504 for details.

Existing Chimney Condition Examine existing chimneys and report defects. Carry out hammer test to existing render. Rebuild defective chimney where required. New render on s.s. lath/mesh. Carefully remove defective lead flashings Repair or replace defective copes. Repoint existing terminals - cans. Replace defective terminals - cans. Details: See dwg. no.18-517/508, 509 & 510 for details.

Chimney Flashings All flashings to be in conjunction with the Lead Sheet Details: See dwg. no.18-517/508, 509 & 510 for details.

Cast Iron Rooflight Carefully remove cast iron rooflight and infill and make good accordingly. Utilise treated timber dwangs and treated sarking. Dwangs at infill to be 100x50mm treated timber.

11. Eaves Protection System Ubbink Eaves protection system fitted adjacent to gutter UPVC Colour: Black Specification: Fully in accordance with manufacturers recommendations, see Ubbink technical details. Detail: See dwg. no.18-517/502 for details.

Existing Rain Water Gutter Carefully Remove Existing Rain Water Gutters. Down pipes to be retained.

12. Rainwater Goods Deepflow UPVC Rainwater Gutter New Gutter Connected to Existing R.W.P. Remove all debris and Clean Gutters and Test for Leaks on Completion of Work

13. Soil and Vent Pipe and Waste Pipe Soil Stack Terminal offset to be retained (already amended as part of EWI project). See dwg. no. 18-517/505 for details.

New Underlay New underlay - undertiling felt. Reinforced felt type 5U to BS 747. min. horizontal lap 100mm min. vertical Lap 150mm Min. Fully in accordance with manufacturers recommendations.

15. Counter Battens Size: 38x25mm treated timber counter batten. Counter batten centres to match existing

rafter or truss centres where possible. Tile Battens

Size: 50x25mm JB Red treated tile battens. Tiling
Headlap min. 75mm in accordance with manufacturers

recommendations. Pitch and overlap to be checked on site.

Fixing
All tiles fixed with tile clip and nail in accordance with manufacturers recommendations.

Existing Sarking - Fragile Roof Material

Existing timber sarking to be retained where still in good condition. Note: Sarking to be investigated on site and agreed with Architect and Clerk of Works.

20. TV Aerials/Satellite Dishes

Aerials and satellite dishes are to be temporarily removed and fixed to the scaffold by a reputable aerial conractor. Residents must be consulted during this operation to ensure that good reception is retained at all times. At the completion of the contract when aerials/satellite dishes are put back the residents should again be consulted to ensure good reception before the scaffolding Existing Fascia and Soffit Retain existing concrete fascia/soffit.

22. Existing Rafters Check existing rafter centres. Note: Structural Engineer to check rafters/truss on site due to additional load from roof

23. Roof Pitch

Check existing roof pitch.

24. Timber purchasing ISO 14001 All timber must be obtained from fully verifiable Forest Stewardship Council FSC or Pan European Forest Certification PEFC.

Waste Management The Contractor must adopt a waste management system. Waste Management to be carried out on or off site. The Contractor must confirm in writing the type of waste management system used

26. Chimney - Gas Flue and Terminal Check existing gas terminals and report findings. Refix loose terminals or replace defective terminals

27. Existing Gas Appliance Check existing appliance and carry out safety check where All in accordance with Current Gas Regulations and Landlords Safety Records.

28. <u>Downtakings</u> Strip off existing roof tiles, tile battens and undertiling felt. Carefully remove any damaged existing sarking boards.

29. Chimney Demolition to BS 6187 (if required) Carefully take down existing redundant chimney, copes, terminals and lead flashings. Contractor to submit work method statement for approval prior to commencing demolition work. Method statement to be submitted and agreed.

30. <u>Asbestos Based Materials</u> Sample panel to be taken for analysis. Copy of the Analysis Report must be sent to the CASO. The safe removal and disposal must be carried out by an Approved Licensed Contractor. Method Statement will be required for approval prior to commencing work.


31. Existing Cold Water Storage Tank Check existing cold water storage tank in roof space and report findings/defects Extend overflow pipe from cold water storage tank. System to be checked on site by Contractor.

32. Existing Windows, Cills Frames and Glass When scaffold is removed clean down and wash all windows, cills, frames and glass on completion.




DRAWINGS ARE INDICATIVE ONLY, BASED ON ORIGINAL TYPICAL TYPE DETAILS.

ALL DIMENSIONS TO BE CHECKED ON SITE.



TILES, VERGE TILE, DOWNPIPES, SARKING, TILE LAPS, FASCIA/SOFFIT AMENDED. NOTE ADDED CONFIRMING STRUCTURAL ENGINEER TO CHECK TRUSSES. STATUS AMENDED.



APRIL 2018


29.11.18


1.01.19


2.06.19

200












CONTRACT


CLOSER NOT REQUIRED) AND STATUS AMENDED. Checked/Date File Ref. **CLEPINGTON ROAD PHASE 1** 18-517 **ROOF RENEWAL** Drwg. No. City Council Title VERGE DETAIL 503 City Development City Architects Checked Scale Date Rev. Division 1:5@A3 30.01.19 Dundee House, 50 North Lindsay Street, Dundee, DD1 1LS Tel: 01382 434000


All timber is to be from the following source, in order of preference (1) Recycled wood and (2) FSC, PEFC, CSA, SFI certified as approved by DEFRA. The Council will not accept timber which has been illegally logged Reproduction by permission of Ordnance Survey on behalf of HMSO, © Crown Copyright and Database Right 2011. All rights reserved. Ordnance Survey Licence No. 100023371


















A STATUS AMENDED.

2.06,19

Revision Checked/Date File Ref. **CLEPINGTON ROAD PHASE 1 ROOF RENEWAL** 18-517 Orwg. No. City Council SIDE CHIMNEY FLASHING DETAILS City Development 510 City Architects Checked Date Division 1:5@A3 30.01.19 Dundee House, 50 North Linusay Street, Dundee, DD1 1LS Tel: 01382 434000

All timber is to be from the following source, in order of preference (1) Recycled wood and (2) FSC, PEFC, CSA, SFI certified as approved by DEFRA. The Council will not accept timber which has been lilegally logged Reproduction by permission of Ordnance Survey on behalf of HMSO, © Crown Copyright and Database Right 2011. All rights reserved. Ordnance Survey Licence No. 100023371

CONTRACT




All timber is to be from the following source, in order of preference (1) Recycled wood and (2) FSC, PEFC, CSA, SFI certified as approved by DEFRA. The Council will not accept timber which has been illegally logged Reproduction by permission of Ordnance Survey on behalf of HMSO, © Crown Copyright and Database Right 2011.


All rights reserved. Ordnance Survey Licence No. 100023371

STATUS AMENDED.

2.06,19



CONTRACT




All timber is to be from the following source, in order of preference (1) Recycled wood and (2) FSC, PEFC, CSA, SFI certified as approved by DEFRA. The Council will not accept timber which has been illegally logged Reproduction by permission of Ordnance Survey on behalf of HMSO, © Crown Copyright and Database Right 2011.

All rights reserved. Ordnance Survey Licence No. 100023371

A STATUS AMENDED.

12.06.19



CONTRACT

APPENDIX 3

Complaints Regarding Clepington Road Phase 1 – Page 67

This page is intentionally letter blank

From:

Sent: 02 December 2021 18:01

To

Subject: RE: Sorry about that just to say have a few concerns from the older residents about tiles sitting on the roof in back green ready to slip down can you please Corden of the areas affected with some tape just so they can stay clear of that zone walking ther

Thank you.

I as noted earlier I will come along tomorrow to see for myself.

Regards

Acting Head of Construction Neighbourhood Services Dundee City Council

e

- 33

Sent: 02 December 2021 17:58

To: dundeecity.gov.uk>

Subject: Re: Sorry about that just to say have a few concerns from the older residents about tiles sitting on the roof in back green ready to slip down can you please Corden of the areas affected with some tape just so they can stay clear of that zone walking ther

I have contacted the papers and my Mp and forward your email to both of them .to be honest if this is not a priority then god knows . have you seen the way the tiles are sitting on the south side there ready to slip down at any time . this has been like this for a week tomorrow and done .when you see them think you Will agree with me .at least Corden it of first thing in the morning .then people Will know not to go in that zone .do yer self a favour don't throw yer under the bus on this one .I cleared up the broken tiles and the big concrete ridge tiles . Old people are worried as its not the first this has happened .4 came flying off in February 2020 .and 3 Landed on the pavement and one in the gutter . Cheers .

On Thu, 2 Dec 2021, 17:41 wrote: Thank you for your reply. I am very much aware and share all health and safety concerns but you will appreciate that a scaffold access is required to get to the roof. I have to be equally attentive to the health and safety of my repair team. We will attend to all affected locations as quickly as possible. Regards **Acting Head of Construction Neighbourhood Services Dundee City Council** e m From Sent: 02 December 2021 17:18 dundeecity.gov.uk> Subject: Re: Sorry about that just to say have a few concerns from the older residents about tiles sitting on the roof in back green ready to slip down can you please Corden of the areas affected with some tape just so they can stay clear of that zone walking ther Its not a priority tiles are sitting on the roof . people are concerned that they slip off in to the back green . I know it's not your fault but tiles flying of the roof and landing in gardens .im sorry but I'll going to contact my Mp and the papers. this totally unexcepable .if the job was done right in the first place .we would not have this situation. does someone have to get killed before its priority On Thu, 2 Dec 2021, 16:46 As I have not been able to fully read your message I would respond as follows meantime. I have a very limited resource who are presently assessing the numerous locations city-wide that have experienced similar storm damage issues.

Whilst I appreciate your concerns my team's initial comment is that your block is not a priority risk when compared to some others.

That said I will look to send a long a small team as quickly as possible to review and look at requirements/implications for cordoning off and removing any grounded tiles.

You will appreciate that the height of the block will require scaffold access to remove any remaining debris.

I will try to get along tomorrow at some point to see for myself.

Regards

Acting Head of Construction Neighbourhood Services Dundee City Council

om nt: UZ December :	<u>dundeecit</u>	v.gov.uk>			
bject: Sorry abou	τ τη τη just το say have a fe slip down can you please	ew concerns from	the older res	idents about tiles sitt	ting on the roo
ar of that zone w	alking there	corden or the ar	eas affected t	with some tape just s	o they can stay
	· · · · · · · · · · · · · · · · · · ·				
	6				
	33				
		1			
				ili. Same	
				80.	
	\mathcal{D}				
		Į.			

From:		

Sent: 03 December 2021 13:41

To

Subject: RE: Sorry about that just to say have a few concerns from the older residents about tiles sitting on the roof in back green ready to slip down can you please Corden of the areas affected with some tape just so they can stay clear of that zone walking ther

Thank you. We already have those tiles logged on the system.

I am also pleased that the guys have been able to cordon off the area so quickly.

Regards

Acting Head of Construction Neighbourhood Services Dundee City Council

е:

m

From

Sent: 03 December 2021 13:38

To: dundeecity.gov.uk>

Subject: Re: Sorry about that just to say have a few concerns from the older residents about tiles sitting on the roof in back green ready to slip down can you please Corden of the areas affected with some tape just so they can stay clear of that zone walking ther

Rob there are tiles missing at the back of the chimneys on 218 facing West road side .its all Cordened now cheers your only covering your self by doing it .

On Thu, 2 Dec 2021, 16:46

wrote:

As I have not been able to fully read your message I would respond as follows meantime.

I have a very limited resource who are presently assessing the numerous locations city-wide that have experienced similar storm damage issues.

Whilst I appreciate your concerns my team's initial comment is that your block is not a priority risk when compared to some others.

That said I will look to send a long a small team as quickly as possible to review and look at requirements/implications for cordoning off and removing any grounded tiles.

You will appreciate that the height of the block will require scaffold access to remove any remaining debris.

I will try to get along tomorrow at some point to see for myself.

degards
Acting Head of Construction
Neighbourhood Services
Oundee City Council In the second of the se
From:
Sent: 02 December 2021 16:22
dundeecity.gov.uk>
Subject: Sorry about that just to say have a few concerns from the older residents about tiles sitting on the roof in back green ready to slip down can you please Corden of the areas affected with some tape just so they can stay clear of that zone walking there





Gregory Colgan-Chief Executive

Chief Executive's Department 21 City Square DUNDEE DD1 3BY

Email: gregory.colgan@dundeecity.gov.uk

Our Ref:

GTC/FT

Your Ref:

Date:

15 December 2021

Dear

I refer to your email of 7 December 2021.

A response to your complaint about work to the roof at Clepington Road was sent on 15 November 2021 by Robin Presswood, Executive Director of City Development. Mr Presswood upheld aspects of your complaint but also advised you of your right to take your complaint to the Scottish Public Services Ombudsman if you remained dissatisfied.

Mr Presswood also explained that officers planned to take a report to the Council's Policy and Resources Committee, informing elected members that a review of working practices on a number of roofs installed by Construction Services between 2015 and 2019 had concluded that the work did not meet best practice as set out in the British Standards.

That report was submitted to Committee on 26 November and set out:

- · work to be undertaken to bring the affected roofs up to standard
- measures put in place to ensure specification, execution and management of construction works is undertaken to appropriate industry standards
- a wider review of arrangements within the Design and Property Division, Construction Services and Housing - to ensure that new or changed legislative and regulatory requirements are identified and addressed

When the report was discussed by elected members, they also required officers, in addition to the involvement of the Council's internal audit service in the review mentioned above, to obtain an independent and external view. This is to provide assurance that any and all failures identified within the report and any subsequent findings that stem from the further internal and external investigations are fully addressed. Such work should reinforce accountability, transparency and confidence in service delivery. Elected members instructed that this work should be completed as soon as possible, with an update on progress by the end of February 2022 and subsequent referral to the Council's Scrutiny Committee.

While this work is underway it would obviously be inappropriate for me or any other officers to provide further information on responsibility for the situation with the roof works or any action to be taken as a result.







Once the audit work and independent review have been concluded, there will be a further report to Committee and any appropriate action and learning will be taken at that time. For this reason, there is nothing further that I or other officers can tell you at this stage. I am told by colleagues that you have been sending emails on a regular basis. Whilst I understand your frustrations I have advised officers not to respond to matters already covered in your complaint or that may be addressed by the reports, current and future.

As previously advised, should you remain dissatisfied with the handling of your complaint you can still escalate this to the Scottish Public Services Ombudsman. If contacted by the Ombudsman, we will provide details of the work which is underway both to remedy the situation with the roofs and to investigate further the reasons why this happened and any action needed as a result.

Yours sincerely

Gregor Colgan Chief Executive - Service Manager

Telephone Call 17.02.2020 with

telephone call. He provided me with an update and said since the roof has been installed 6 weeks ago, tiles have come off at 216 just last night. I explained we are currently rectifying the tiles which have come off in the severe weather yesterday and scaffolding has been erected for this repair to be carried out. I explained we are responding as we would to any other emergency repair similar.

He highlighted that when he met with the COW on 08.01.2020 they discussed how the tiles had not been nailed to the roof and showed and 7 videos of this. At this interview advised the COW confirmed he had signed off the roof and apologised to for the poor standard. That he had highlighted to that he had not been on the roof. The had promised that he would review this and come back to him within 2/3 days. States he has this conversation recorded which he confirmed with and with the beginning of the conversation.

advised neither responded as promised which was then when he contacted and scheduled an interview with the said this meeting was to try and resolve the issue and again he showed the videos to which agreed the standard was unsuitable. I confirmed it was following this that his complaint was raised as S1. However due to the complexity of this we have escalated his S1 and are now investigating as a stage 2 complaint.

asked me if I thought the roof was safe at this stage and I explained this is what we are currently investigating as part of the S2 and in addition we are reviewing the materials used which he confirmed formed part of his S1 complaint. I explained at this point I do not have an outcome to his S2 but confirmed we will respond as we have on an emergency basis to carry out repairs as required.

said he wanted to be up front and said that today he has contacted the H&S Executive to report his concerns. He also has a meeting tomorrow with his MSP Shona Robison. In addition he has an interview scheduled for tomorrow at 11am with Reporter DC Thomson.

I confirmed as soon as we have reviewed his S2 I will be in contact with him. He highlighted he is available for any further discussions as required. He states he cannot sell his property at this time due to the condition of the roof and he suggested following his FOI that other roofs will be in the same condition.

Statement

– Service Manager

Telephone Call 28.02.2020 with

Telephoned to advise the tiles which came off the roof were reinstated on 19.02.2020. No answer and so voicemail left asking to return call.

16.15

Telephoned to advise the tiles which came off the roof were reinstated on 19.02.2020. He said he was aware. He asked for an update on our investigations which he thinks are ridiculous that they are ongoing. I advised in regards to his overall Stage 2 we anticipate to update him no later than 11.03.2020. He went on to state he never signed anything to escalate to Stage 2 and I explained he did not need to and where an issue can't be rectified or investigated at stage 1 due to the complexity means we can escalate to Stage 2 (in line with the Obudsman guidance). He said residents are fearful to walk out there house and in addition he has spoke to his solicitor who is concerned no one will get a mortgage on his property and he would need to undertake a cash sale which would mean him losing £15,000. I explained we are taking these concerns seriously and will look to provide a response asap. Meantime we will respond to emergency repairs as we have already.

advised he was watching the roofers at Wedderburn and they had no hard hats, harnesses and are not using the suppression on the "still saws" to cut tiles.

explained this is not good practice and roofers should be undertaking the works in line with H&S. I confirmed I would be noting this to discuss the concerns and take any necessary action with DCS Management Team. (Follow up - Raised with to investigate and f/b).

confirmed he would be updating his solicitor of our telephone call.

	Statement
I	– Service Manager
	Telephone Call 06/03/2020 with
	Advised I was phoning to update him on our discussions earlier that week about Wedderburn observations. I confirmed I raised this with Head of DCS. I confirmed their response was:
	1. The men had their hard hats up on the scaffold with them, it is not a requirement under H&S regs. to wear them on the roof.
	2. The use of a harness is not required as the working platform of the scaffold forms the fall arrest system to protect the men.
	3.The men have got the water bottles for the dust suppression with them at all times, it is stated with in the risk assessment they must be used.
	A reminder has been given to all to ensure they use dust suppression and adhere to H&S. The Teams will monitor this going forward. Said DCS were us and this is not the case. He knows H&S regs and the trades are not adhering. In addition he states they didn't adhere when they were on site at Clepington Road.
	In relation to his Stage 2 I explained throughout this week we have been attempting to conclude the complaints relating to Clepington Road roofs and discussed with Heads of Housing, City Dev and DCS. However there are further enquiries which need to be carried out before we can conclude matters and so it is unlikely we will meet the S2 outcome of 11.03.2020 and instead would hope to conclude on 16.03.2020. was not satisfied with this update and thinks we are "dragging our heels due to costs". He asked why said back on 08/01/2020 that this was a serious matter and he would get f/b in a few days which he never. I apologised for this. He said the longer this takes the more he cannot sell his house as no one would get a mortgage and loose money on cash deal.
	said he knows what the figures are and said it would cost around £200k to conclude this from installation to repairs. I tried to assure him that the decision doesn't come down to cost. The investigation will look at the complaint in its own merit to assess and come to an outcome regardless of cost. But to conclude matters we need to ensure we have reviewed matters in the entirety so we can clearly explain and conclude his complaint.
	advised he has the spec for the batons used and said we "shouldn't embarrass ourselves" as he know they are not to standard. I confirmed we are reviewing materials used along with the evidence as part of his complaint. In addition he said the letter he signed for the grant said a building warrant should have been obtained for this roof and he cannot identify if one was sought. Confirmed I would look into.
	concluded by stating he was sending a letter direct to David Martin along with a memory stick with the videos of the loose tiles. He thinks about 90% are loose. He confirmed he is sending this recorded delivery.

Thanked

for his time.





David Simpson Head of Housing & Communities

Neighbourhood Services 5 City Square Dundee DO1 38A

Tel: Ema

Our Ref:

DS/EH

Your Ref.

Date:

19 March 2020



Roof Replacement – 212-220 Clepington Road, Dundee Stage 2 Complaint Ref 9722

I refer to your recent complaint about works to renew the roofs at the above location and my most recent letter, dated 13 March 2020.

I felt that it was appropriate to further update you that due to the impact of the current Coronavirus outbreak on all Council services I am unable to say when our investigations into the issues around these roofs will be concluded.

We remain committed to resolving this matter as soon as possible but you will appreciate that we are in very challenging times which mean that certain elements of work are having to be prioritised ahead of others.

We will come back to you as soon as we can.

Yours sincerely



David Simpson
Head of Housing and Communities

Copies:

- Service Manager Housing
Service Manager Construction

Head of Design & Property Services







is ok with

Statement - Service Manager Telephone Call 13/07/2020 with on 08/07 regarding a CS Staffing Following receipt of an incident report to incident where it is alleged a member of staff named has on two occasions shouted abuse to him in the street. On the first incident stated drove passed him and shouted from his There was no witnesses to this event. vehicle "You're a On the second occasion, 08/07/2020 around 12.15 when was speaking to his from the private houses across the road drove passed and made a hand gesture and shouted to explained in the first instance he would be satisfied if we addressed this with however if he denies this then he would encourage us to contact his neighbour to verify these events. I confirmed we will investigate and do so in the first instance however write to his neighbour asking she contacts if required. asked for progress on his complaint made pre lockdown. I explained Head of H&C is off this week however I would look to convene a meeting with to confirm a timeline in respect of the response to his and complaint and feedback by 24/07/2020. I advised this is not to conclude the complaint but in fact to advise a timeline for this. 14.07.2020 and advised I have discussed with Head of Telephoned

I advised we will respond to him next week in terms of the timeline for responding to the corporate roofing complaint. He advises we are dragging our feet on this. I explained the impact of Covid-19 delaying the response and we are working in partnership across the services to conclude this. He explained he has spoken to neighbours about their complaints (I highlighted I could not comment on other complaints given the GDPR implications) however he states they collectively will look to take to Solicitors and the press if this is not concluded asap.

Construction Services and the complaint about the conduct of a Construction Services

employee will be investigated as part of our disciplinary processes.

Advised I will discuss with him next week.

this response.





David Simpson
Head of Housing & Communities

Neighbourhood Services 5 City Square Dundee DD1 3BA

Tel: (Ema

Our Ref:

DS/EH

Your Ref:

Date:

19 May 2021



Corporate Complaint 10493

Following our Stage 1 response to your complaint, you confirmed that you remained dissatisfied with the response in respect of the chimney condition at the time your roof was renewed. Your complaint was escalated to Stage 2 of the Councils Complaints procedures.

I have now investigated your Stage 2 complaint. Within my investigations, I reviewed the photographs that you shared with — Service Manager, Housing and have also had these photographs assessed by technical colleagues to determine whether the condition of the chimney within the photographs could have reasonably been in this condition when the roof was renewed. I am satisfied that the evidence you have presented along with the opinion of qualified colleagues that this chimney should have been repaired when the roof was renewed. These repairs have now been carried out at no cost to you or other owners.

Therefore, I uphold your complaint and the service will investigate why this chimney was not repaired at the original roof renewal.

You also requested a copy of the completion certificate which is completed when the roof is finished. I have attached this for your information.

If you are not satisfied with my response, you may wish to take your complaint to the Scottish Public Services Ombudsman who can carry out an independent review. The Scottish Public Services Ombudsman (SPSO) is the final stage for complaints about public services in Scotland. This includes complaints about Scottish Councils. If you remain dissatisfied, you can ask the SPSO to look at your complaint.







The SPSO cannot normally look at complaints:

- where you have not gone all the way through the council's complaints handling procedure;
- more than 12 months after you became aware of the matter you want to complain about, or
- that have been or are being considered in Court.

The SPSO's contact details are:

Freepost SPSO

Freephone: 0800 377 7330

Online contact: www.spso.org.uk/contact us

Website: www.spso.org.uk
Mobile site: http://m.spso.org.uk

Yours sincerely

David Simpson

Head of Housing and Communities

Please tell us about your complaint, including what has gone wrong and what outcome you are seeking

I WISH TO CONPERIN ABOUT MR DAJID SIMPSON

WHO IS IN CHARGE OF COPORATE COMPERINTS, TY COMPRINT

IS THIS MAN IS INCOMPATION IN HIS BOB AND HIS

ATTITIODE. TO THE GENERAL PUBLIC MY SET. HE HAS

FAKEN ZI MONTHS TO INVESTIGATE AS MY ROOF

WAS BOTCHED BY COUNCIL SLATERS OR ROOFERS

AND THE EVIDENCE IS QUITE CCEAR TO SEE.

THE COUNCIL HAVE NOT CARRIED ONT TO BRITISH

COOK STANDARS BY 5534.

If you have already spoken to someone abo	out this complaint, please tell us v	vho and when
Please give us your contact details		
Name		
Address		
Tel No:		
Email:		
and if you would like us to contact someon advisor) give us their contact details	e else about your complaint (e.g.	a relative, friend or
Name		
Address		
Tel No:		
Email:		
4		**************************************
for official use only	Date received	100 L
	Complaint system ref no	
Potura form to: E-conset DCCV DC	IC HCTD	wer proportion of the state of

Return form to:

Freepost RSSY - BELC - USTB

Dundee City Council Customer Services 50 North Lindsay Street

DUNDEE DD1 1QE



Scan here

IN WITCH YOUR LAWYERS HAVE SON THE EVIDENCE AND MY LAWYERS. HE KEEPS TELLING ME IS UNDER INVESTIBLION SURLEY 1. DOES NOT TAKE U MONTHS I HAVE AGKED Him COUNTLESS TIMES TO SEND A COPRATE CONPLAINTS FORM TO ME AND HE REFUSUSE TO DO SO & Have ALSO ASKED HIM FOR AN EXPLANTION WHY HE IS TAKEN UMONTHS AND HE REFUSES TO TELL ME, I HAVE ALSO ASKED Him for our completion CERTIFONIE. FOR THE ROOF AS THE CLEEK OF WORKS HAS SIGNED OFF AS CONFLETE, ALL THE SINEC RESIDENSE HAVE HAD THERE'S COMPLETION CERTIFICATE BUT WEE DON'T HAVE OVES. CON YOU BRIOW. 1/1/15 10 ME. I HAVE ALSO ASK FOR MRS BUIRLAG E. MAIL. AND HE HAS REFUSED. ME, I WONT A COPRAIE COMPLAINT FORM SENT TO ME AS THIS 15 NO A CORRATE COMPAINT FORM. (15 YOUR PUBLIC OUTY TO SEND ME ONE





Neighbourhood Services - Housing & Communities 5 City Square Dundee DD1 3BA

Contact Position Section Tel Email



Date

06 Sep 2021

Dear

Re: Acknowledgement of complaint Reference No. 10851 Complaint subject: Complaint

*** During the pandemic we may not be able to respond to complaints within normal target timescales while officers are focusing on delivering priority services. ***

Thank you for telling us about your complaint. The complaint was registered on Monday, 6th September 2021 and has been passed to the formula of the complaint was registered on Monday, 6th September 2021 and has been passed to the complaint was registered on Monday, 6th September 2021 and has been passed to the complaint was registered on Monday, 6th September 2021 and has been passed to the complaint was registered on Monday, 6th September 2021 and has been passed to the complaint was registered on Monday.

The Council aims to respond to most complaints within 5 working days, so the target for completion of this complaint is Monday, 13th September 2021. If we can't fully respond to your complaint within the target time we will let you know.

If you have any enquiries with regard to the complaint, or you wish to submit further information regarding it, please do not hesitate to contact the member of staff named above at the telephone number shown. Please quote the complaint reference number '10851'.

Throughout this process, you also have the right to seek independent advice from a Citizens Advice Bureau, Advice Centre, solicitor etc if you feel this would be of benefit to you. If your complaint is regarding the Sheltered Housing Service or Housing Support Service you also have the right to complain directly to the Care Inspectorate, Compass House, 11 Riverside Drive, DUNDEE DD1 4NY Tel: 01382 207200.

Yours sincerely











Elaine Zwirlein
Executive Director of Neighbourhood Services

Neighbourhood Services 5 City Square Dundee DD1 3BA

Tel: 01382 434538 Email: elaine zwirlein@dundeecity.gov.uk

Our Ref:

EZ/KK/Corp Comp. 10851

Your Ref.

Date:

10 September 2021



Stage 1 Corporate Complaint 10851

I refer to your complaint, received 6 September 2021, regarding your roof and the Head of Housing & Communities responses to your various enquiries.

Having reviewed your various emails to Mr Simpson, I am satisfied that he has responded appropriately, based on the information available, on your substantive issue - the standard to which the roof replacement at your address has been completed.

Mr Simpson has advised you that this matter remains under investigation and that you will be advised once the investigation is complete. While I would accept that it has taken longer than desired to resolve this matter I would point out that we have had a global pandemic during this period and this has impacted on this and other matters.

Mr Simpson has dealt with your emails when received and has tried to explain that you do not need to fill out a corporate complaints form for us to consider your concerns.

Regardless of this offer, he recently sent you the paper copy of our complaints process which you have now used and to which I am responding today.

Our normal practice is to issue a letter to residents at the point of practical completion but I note that Mr Simpson has provided you with a copy of the practical completion certificate for the works undertaken following a request from you. Having taken advice from the Council's Information Governance Manager, the copy that you were sent was redacted to remove any personal sensitive data relating to staff involved in the preparation of the certificate.

Having reviewed the relevant information, I am satisfied that Mr Simpson has responded to your various enquiries and has accurately advised you regarding the ongoing investigation into the works at your roof.

I will ensure that you are advised of the outcome of the investigation once this is available.

As a result of the above, I do not uphold your complaint.







If you are not satisfied with this response, you have the right to have your complaint considered by Robin Presswood, Executive Director of City Development, Dundee City Council, Floor 6, Dundee House, 50 North Lindsay Street, Dundee DD1 1LS [e-mail: robin.presswood@dundeecity.gov.uk). Should you wish to do this, you should write or e-mail the Executive Director of City Development stating your reasons and a reply will be sent to you within 20 working days.

Full details of our Complaints Procedure are available online at www.dundeecity.gov.uk/complaints or you can pick up a leaflet at any Council office.

Yours sincerely,

Elaine Zwirlein

Executive Director of Neighbourhood Services





Executive Director City Development

Dundee House, 50 North Lindsay Street, Dundee DD1 1LS

If calling, please ask for Robin Presswood, telephone 01382 433610

Email: robin.presswood@dundeecity.gov.uk

Our Ref: RP/KAS

Your Ref:

15 November 2021

Dear

CORPORATE COMPLAINT REFERENCE NUMBER: 10851

Many thanks for taking the time to speak to me on Tuesday 2 November 2021. I am grateful that you gave me the opportunity to understand your perspective on the complaint that you have raised.

In my email of 4 October, I defined the focus of the Stage 2 complaint as being:

- 1. failure to adequately fix the roof during the communal roof replacement at 214 Clepington Road;
- 2. your belief that the failure to comply with the British Standard is a breach of Health and Safety Regulations; and
- 3. your request that the council supply a copy of the completion certificate for the works done on the communal roof at Clepington Road.

When we met you also highlighted your concern about the Council's failure to carry out remedial works to the chimneys on the communal roof. I indicated that although I shared your concern about this matter, as it had already been considered by David Simpson in his response to your corporate complaint (19 May 2021) in which he upheld your complaint, we could not consider this matter again as part of this corporate complaint.

I asked you what remediation you were seeking from the complaints process, and you highlighted first and foremost a desire to see the works carried out as soon as possible to bring the roof into line with the appropriate British Standard.

I indicated that my complaint resolution would look at each of these issues in turn, and at the end of it we would include text of your right to appeal to the Scottish Public Services Ombudsmen, but you indicated your intention to take your complaint to the tribunal under the Property Factors (Scotland) Act 2011 in the event that you cannot get satisfaction from the Council's complaints process. Thank you again for providing additional information on this in follow up emails the same day.







15 November 2021

I have considered each aspect of your complaint and my response is as follows:

 failure to adequately fix the roof during the communal roof replacement at Clepington Road.

The Council has been considering this matter extensively since the issue was first identified in 2019. This review has taken a considerable period of time, and I know this has been frustrating for you. I apologise for the length of time it has taken to conclude this matter – as you can imagine there has been a significant impact caused by COVID-19 and the need to take independent advice.

I am now able to confirm that the Council will consider a report at the Policy and Resources Committee on Monday 22 November 2021, which addresses this matter. The report concludes that the investigated roofs do not fully comply with BS 5534 in respect of how the tiles are fixed to the roof structure. The concrete roof tiles were not fully mechanically fixed.

The recommendations in the report include that the Council should carry out works to bring the affected roofs (a total of 450 roofs) up to the standard recommended in British Standards.

I therefore uphold this aspect of your complaint.

your belief that the failure to comply with the British Standard is a breach of Health and Safety Regulations.

The Council takes its duties under the relevant Health and Safety legislation extremely seriously, and has reviewed this aspect of the issue very thoroughly. As you may be aware, British Standards are not legally binding, but do represent best practice, and the Council normally seeks to comply with them. The works carried out on the affected roofs does comply with the pre 2015 British Standard.

As part of the investigations both by Council Officers and the BRE, wind speed data was obtained from the Tay Road Bridge records to determine wind loading experienced by roofs in service since 2015 that were not installed to the current requirements of BS5534. The data indicated that there had been significant wind events during the period in question that may have resulted in anticipated roof damage. Notwithstanding the non-compliance with BS5534 for fixings requirements, the affected roofs had not experienced consequential tile loss during this period. Reported individual roof tile defects on the affected roofs are tabulated below for information.

Year	2015	2016	2017	2018	2019	2020	2021
Recorded Roof Tile Defects	1	1	0	0	0	4	0

The opinion is that the non-compliance in fixings presents no short-term integrity concerns. However, it is recognised that these roofs will require remedial works to bring them to full compliance for long-term integrity.

As there is no evidence of any Health and Safety issues caused by the failure to update working practices, I do not uphold this aspect of your complaint.

15 November 2021

3. your request that the council supply a copy of the completion certificate for the works done on the communal roof at Clepington Road.

We discussed this matter during our phone call. I highlighted that David Simpson, the Head of Housing and Communities had previously supplied you with a Completion Certificate in his email of 19 May 2021 in which he upheld that complaint. I understand that the completion certificate supplied is the normal document for this type of works.

I hope that this is helpful.

The Scottish Public Services Ombudsman (SPSO) is the final stage for complaints about public services in Scotland. This includes complaints about Scottish councils. If you remain dissatisfied, you can ask the SPSO to look at your complaint.

The SPSO cannot normally look at complaints:

- where you have not gone all the way through the Council's complaints handling procedure
- more than 12 months after you became aware of the matter you want to complaint about, or
- that have been or are being considered in court

The SPSO's contact details are:

SPSO, Bridgeside House, 99 McDonald Road, Edinburgh, EH7 4NS

Freepost SPSO

Freephone: 0800 377 7330

Online contact www.spso.org.uk/contact-us

Website: www.spso.org.uk Mobile site: http://m.spso.org.uk

Full details of our Complaints Procedure are available online at

www.dundeecity.gov.uk/complaints or you can pick up a leaflet at any Council office.

Yours sincerely

ROBIN PRESSWOOD

Executive Director of City Development





Roger Seaman, Housing Asset Manager

Neighbourhood Services West District Office 3 Sinclair Street Dundee DD2 3DA

Date:

Email
Our Ref:

09 February 2022

Dea

Stage 1 Complaint: 9722


Further to my earlier response I am still waiting on an update from my counterparts in Environment Department Construction Services and City Development and hope to have a response soon which answers all your points.

Yours sincerely



Copy to:

Housing Asset Management Unit









This page is intentionally left blank.

APPENDIX 4

Completion Documentation for Camperdown 2nd Development and Clepington Road Phase 1

Clerk of Works Weekly Report Week ending 30 October 2015 Camperdown Roof Replacement Second Phase

Certificate of Practical Completion Camperdown Roof Replacement Second Page 95 Phase

Clerk of Works Weekly Report Week ending 13 December 2019 Clepington Page 96 Road Development Phase 1

Certificate of Practical Completion Clepington Road Development Phase 1

Page 99

This page is intentionally left blank

		Project	l'itle/	Description
Camperdown	Roof	Replacement	2 nd	Phase

CLERK OF WORKS WEEKLY REPORT

GENERAL

PERSONNEL	
Project Administrator	
Contractor	ECS
Clerk of Works	
Site Supervisor	

Report Number	10
Week Ending	30/10//2015
Contract Start Date	10/08/2015
Contract Completion Date	19/10/2015
Progress Against programme	On programme

Weather Report	Day	A.M.	°C	P.M.	° C	Man hours lost
	Monday	Fair	6	Sun	11	
	Tuesday	Fog	12	Drizzle	12	
	Wednesday	N/A				
	Thursday					
	Friday					
	Saturday					
	Sunday					
	Total man hou					
	Total to date					

INFORMATION

INFORMATION	
Drawings and info required	
(if none write none)	
Attachments to Report	
(if none write none)	
¥.	
Difficulties	
(including shortages which may	
cause delays and action taken)	
234 4-25	
Digital Photo Record	
Visitors	

Project	Reference	
-		

Work	%	Work	%	Work	%	Work	%
Preliminaries		Suspended Floor		Plastering		Ceiling grid/tiles	
Downtakings		Roof Structure		Render		Decoration	
Excavations		Roof Coverings		Plumbing 1st fix		External works	
Piling		Brick/Block Ext		Plumbing 2nd fix		Lifts	
Foundations		Brick/Block Int		Floor Screed		Mains : Gas	
Concrete Structure		Joiner 1st fix		Electrical 1st fix		Electric	
Steel Erection		Joiner 2nd fix		Electrical 2nd fix		Water	
Ground Floor		Cladding		H&V 1st fix		Telecom	
Drainage		Window/glazing		H&V 2nd fix		Defects/Handover	
Timber Frame				Floor coverings			

GENERAL REPORT

26/10/2015

Scaffold still up at number 38.

27/10/2015

Scaffold removed all works completed .

- 3 houses remain to be done because of stoppage due to Electrical Cables overhead
- 1 Brownhill Place
- 7 Brownhill Place
- 13 Liff Crescent.

Any incidents contrary to good environmental management practice	(yes/no)	
Use waste from construction sites form F535	(yes/no)	
Use sustainable timber form F530	(yes/no)	

CIRCULATION	DATE		DATE
Received by Principal Clerk of Works		Received by Project Administrator	
			·

Clerk of Works	30/10/2015

Project Title: CAMPERDOWN 2ND DEV ROOF RENEWALS, DUNDEE

Certificate of

Practical Completion

Client: Director of Housing
Address: floor 1 Dundee House

Project Ref:15/513/GBP

Contractor: Environment Department

Certificate No: 01

Address:

Dundee City Council, 353 Clepington Road, Dundee

Issue Date: 25/07/16

Contract Dated:

10/06/15

Under the terms of the above-mentioned Contract.

I/we hereby certify that Practical Completion of


†Delete as appropriate

ALL WORKS

was achieved on

25TH July 2016

Building Warrant Applicable and Obtained	Yes	Date	N/A X
Electrical Certificate of Compliance Obtained			×
Building Control Certification of Completion Applied For			х



F 022 CLERK OF WORKS WEEKLY REPORT

Client Ref			Project	1100	2500	2 0 6 9 6	· · · · · · · · · · · · · · · · · · ·			
To be comp	eleted b	y lead CC	W's	1		ſ	2550350 To	o be completed b	y all COW's	
	_				GENER/	<u> </u>		•		
	PERS	ONNEL	-		GENERA		ort Number	OC. 160-7616, 160-9	9	
Supervising Officer	1 2110		track and the	de Fille			sek Ending	13/12/2019		
Contractor	edcs	a Principle (See)	25100.00		000786 (4)		act Start Date		0/2019	
Clerk of Works	3000		Park Selection				ct Comp. Date		tbc	
Site Supervisor							ed Comp. Date	PERSONAL PROPERTY.		
Site Phone No						Progress Against Prog. Emergency Phone No.		APRICATE AND		
				MEA	TUED D					
Day				WEA M	THER R	C I	PM	°C	I Haves I and	
Monday	,			ry		ry	FIVE	- Constructible stated in the same	Hours Lost	
Tuesday				ry		in				
Wednesd				TV	100000000000000000000000000000000000000	in				
Thursda	•		-	V	Or Constitution of the last	wers		COLUMN TO THE		
Friday	,			ry	1000	ry				
Saturday	v			1000ae	CO CONTROL					
Sunday		-		Acceptant						
#3 = =			Total Ho	urs Lo	st (in week)	STENSOR MESTRA	200 (0.00)	A TOTAL CONTRACTOR OF THE PARTY	Entra Contractor Contractor	
100					st (to date)		***			
Duandana and lat			Dispersion of these	IN	FORMA	ION				
Drawings and inf	_	rea	表別など		BEIGHT AND			The Two Established		
(if none write		·	TOTAL PROPERTY.			Ly practice		0.1500.00744	E46.00G 60G 505	
(if none write	-		37-100 mg/m						LESS BUILDING	
Difficulties (including s		e which	SARRY BY AN	A HEREAN	gardenning 2.00 True south the left of		TOTAL DESIGNATION			
may cause delays an	-		A ALEXA ASS							
Digital Photo		taton	MITTER STATE		Editor Car	e appropriate				
2.3			March 200							
Visitors	3		1.000			CONTRACT				
			Western							
			LIBABAA	7V 0	EWORK	IN DOC	ODEGO		TOTAL SECURE PROPERTY.	
	1 %	7 3	UMMA	N 1 0	F WORK	IN PHO	OGRESS		1 0	
Preliminaries	10	Patent i	Roofing	986338	Down Ta	king	%	Gas Mains	%	
Excavations	106220	Steel E		\$260MG	Floor Co		202000000 013900000	Electric Mains	26252	
Concrete Foundations	262-1520	Timber		200,000	Floor So		2830622	Water Mains	202240 data-per	
Piling	10000000	Joinery		2375.23	The second second	pplication	21240000	Telecom Mains	200	
Foundations	1653/7	Joinery		50.0-60	Lifts	ppiicatioi	-0.054603	External Works	204.740 204.014	
Asphalt Tanking	250000	Window		0.00.00	the Late		5000000	Electrical 1st Fix	30000	
	0.000000	Glazing		3/22-42			5,48000	Electrical 2 nd Fix		
Asphalt Roofing	19:450-670	Plasteri		Const	90		2.55 AA	Heating 1st Fix	94954	
Asphalt Roofing Brickwork/Block External	GRADOWS.	Metalwo	•	202000	200			Heating 2 nd Fix	2000	
Brickwork/Block External	-759450A-63	Decorat		10800	200	77,7	0.000000	Ventilation 1st Fi	0000000 0000000	
Brickwork/Block External Brickwork/Block Internal	1653953	Ceiling grid/tiles		195701			4080000	Ventilation 2 nd F		
Brickwork/Block External Brickwork/Block Internal Drainage	200	Ceiling	Roof Structure		0.00		27.50	Water 1 st Fix	Tenan	
Brickwork/Block External Brickwork/Block Internal Drainage Paving and Flooring	10000	-	ructure		200		140000000	Water 2 nd Fix	200000	
Brickwork/Block External Brickwork/Block Internal Drainage		-		187926	63			STREET LIA		
Brickwork/Block External Brickwork/Block Internal Drainage Paving and Flooring Masonry		Roof St Roof Co	vering				35564.0		ver	
Brickwork/Block External Brickwork/Block Internal Drainage Paving and Flooring Masonry Slater and Tiler		Roof St	vering				1667	Defects / Hando	ver	
Brickwork/Block External Brickwork/Block Internal Drainage Paving and Flooring Masonry Slater and Tiler Suspended Floor Concrete Structure		Roof St Roof Co Claddin Render	overing g					Defects / Hando Commissioning		
Brickwork/Block External Brickwork/Block Internal Drainage Paving and Flooring Masonry Slater and Tiler Suspended Floor Concrete Structure	NCIDE	Roof St Roof Co Claddin Render	overing g	RY TO	O GOOD	HEALT	H AND SAFE	Defects / Hando		
Brickwork/Block External Brickwork/Block Internal Drainage Paving and Flooring Masonry Slater and Tiler Suspended Floor Concrete Structure	NCIDE	Roof St Roof Co Claddin Render	overing g	RYTO	D GOOD	HEALT	H AND SAFE	Defects / Hando Commissioning		
Brickwork/Block External Brickwork/Block Internal Drainage Paving and Flooring Masonry Slater and Tiler Suspended Floor Concrete Structure	NCIDE	Roof St Roof Co Claddin Render	overing g	RY TO	D GOOD	HEALT	H AND SAFE	Defects / Hando Commissioning		

	THIS WEEKS PROGRESS SUMMARY
Date	Report
	no 212-214-216 clepington rd
	roof now 100% completed
	roof now passed and scaffold can be dropped
	scaffold now,being dropped
	no 218-220 clepington rd
DIA SERVICE	tiling now 100% completed
	tiling now 100% completed roof now passed and scaffold can be dropped
SALES AND AND ADDRESS OF THE PARTY OF THE PA	root now passed and scarroid can be dropped
4007	
SALE:	
NAME OF	
17.00	
53696.23	
	35. ACC A MAN AND AND AND AND AND AND AND AND AND A
44-	
Transact.	
Repair :	
New York	
TOURS.	
-	
STATE OF	
- date	
r en	
No Section	
ZILVERY ORSE	

	No.
16/12/2019	

Certificate of

Project Title: Clepington Road Development Phase 1, Dundee - Re-roofing

Practical Completion

Client:

Director of Housing & Communities

Address:

Dundee House, Dundee

Contractor:

Environment Dundee Contract Services

Address:

Dundee City Council, 353 Clepington Road, Dundee

Certificate No: 01
Issue Date: 20.12.2019

Project Ref: 18-517

Contract Dated:

5th June 2019

Under the terms of the above-mentioned Contract.

I/we hereby certify that Practical Completion of

†Delete as appropriate

To be signed for and

ALL WORKS

was achieved on

20th December 2019

Building Warrant Applicable and Obtained	··-	Yes	Date	N/A X	
Electrical Certificate of Compliance Obtained				х	
Building Control Certification of Completion Applied For				Х	

on behalf of the	issuer									
named below		Signed				·				
Distribution Original to:		Copies		.	<u> </u>		···	DUNDEE CITY	COUNCIL	_
x	Client	to:	Contractor	M&E	E Services		City Development	ARCHITECTURAL Ray Low City Architectural Floor 5 Dundee Ho South Lindsay Stre	SERVICES Services Officer	
	**	X	Quantity Surveyor	Engi	ineer			Telephone: 01382 Fax: 01382	43 3380 433263	
	City Dev		Nominated Sub- Contractor	X Clerk	k of Works	x	File			

this are intentionally letter blank