REPORT TO: DEVELOPMENT QUALITY COMMITTEE - 27 JANUARY 2003

REPORT ON: BUILDING (SCOTLAND) ACT 1959

SECTION 13 - DANGEROUS BUILDINGS

REPORT BY: DIRECTOR OF PLANNING AND TRANSPORTATION

REPORT NO: 47-2003

1 PURPOSE OF REPORT

1.1 To advise members of the action taken in dealing with dangerous buildings during the month of October 2002.

2 RECOMMENDATIONS

2.1 It is recommended that Committee note the contents of this report.

3 FINANCIAL IMPLICATIONS

3.1 All costs incurred in taking direct action, including staff time and administration charges, will be recovered from individual owners.

4 LOCAL AGENDA 21 IMPLICATIONS

4.1 Ensuring that buildings are maintained in a safe condition will contribute towards Key Theme 8 by creating a safe and pleasant environment.

5 EQUAL OPPORTUNITIES IMPLICATIONS

5.1 There are no equal opportunities implications of relevance to this report.

6 BACKGROUND

6.1 **Dangerous Building Notices**

The City Engineer investigated 15 incidents relating to public safety of dangerous buildings during the month of October 2002. During this period no formal Notices were issued under Section 13(1c) of the Building (Scotland) Act 1959.

6.2 **Direct Action Taken**

Direct action has been taken in 5 instances to ensure Public Safety is maintained under Section 13(1b) of the Building (Scotland) Act 1959.

6.2.1 <u>47 Dalhousie Road</u> - Barrier erected at damaged retaining wall

Mrs I Craig

6.2.2 <u>221 Hilltown</u> - Removed loose masonry from façade

Broomfield Nurseries 3 Albert Road Broughty Ferry Dundee DD5 1AY Report No 47-2003

2

6.2.3	223 Hilltown (Flat 1/1)	-	Removed loose masonry from façade
	Shepherds 13 Albert Square Dundee On behalf of Mr & Mrs Brown		
6.2.4	223 Hilltown (Flat 2/1)	-	Removed loose masonry from façade
	Abdul Aziz Bhimani & Zebunisa Bhima 17 Invergowrie Drive Dundee	ni	
6.2.5	223 Hilltown (Flat 2/2)	-	Removed loose masonry from façade
	Tein Khuong Tran 11 Vorlich Avenue Broughty Ferry Dundee		
6.2.6	223 Hilltown (Flat 3/1)	-	Removed loose masonry from façade
	Hamza Aziz & Hussein AZIZ 13 Greystone Avenue Leicester		
6.2.7	223 Hilltown (Flat 3/2)	-	Removed loose masonry from façade
	Steven Bernard McLean 4 Baldragon View Dundee		
6.2.8	223 Hilltown (Attic)	-	Removed loose masonry from façade
	Mr Cuthbertson Top Flat 223 Hilltown Dundee		
6.2.9	225 Hilltown	-	Removed loose masonry from façade
	Mohammad K Yousaf 172 Glamis Road Dundee DD2 2EW		
6.2.10	98 Alexander Street	-	Board over all broken windows and secure gates into the yard area.
	ZIKA Rapid Distribution Ltd 25 North Row London		
6.2.11	7 Rosefield Street, Flat 1/1	-	Board over broken windows
	Mr M Mathews Quarry Cottages Inchture		

6.2.12 <u>45 Commercial Street</u>

Board over broken windows

Mr D Barr C/o D & A Motor Factors 2-4 West Henderson Wynd Dundee

6.3 Advisory Letters Issued

Letters were issued to owners advising them to have their properties inspected and to undertake the necessary repairs to the following properties.

- 6.3.1 42 St Mary's Road Leaning garden wall
- 6.3.2 <u>100/108 Commercial Street</u> Loose Masonry
- 6.3.3 <u>88 St Vincent Street, Broughty</u> Loose Masonry Ferry

7 CONSULTATIONS

7.1 The Chief Executive, Director of Finance, Director of Support Services and Director of Corporate Planning have been consulted and are in agreement with the contents of this report.

8 BACKGROUND PAPERS

8.1 There are no background papers of relevance to this report.

Mike Galloway Ken Laing
Director of Planning & Transportation City Engineer

KL/EH 17 January 2003

Dundee City Council Tayside House Dundee