

POLLING PLACE AUDIT

POLLING PLACE: PANMUREFIELD VILLAGE CHURCH, LAWERS DRIVE

REFERENCE NO 106

1. ACCESS AUDIT

(a) Car Parking

- | | | |
|----|--|-----|
| 1. | Is parking available nearby and with ample room to open car door (i.e. 3.4m)? | YES |
| 2. | Alternatively, is there a dropping off zone again with ample room to open door? | N/A |
| 3. | Is there a dropped kerb to allow access to main door from parking/dropping off area? | YES |
| 4. | Are the road/pavement surfaces level and of good quality (e.g. no potholed)? | YES |

(b) Access to Premises

- | | | |
|----|--|-----|
| 1. | Is the access on the flat? | YES |
| 2. | <u>Are there any steps to main door (if yes - how many)?</u> | NO |
| 3. | If there are any steps, is there a handrail? | N/A |
| 4. | Is there a ramp? (Gradient 1:) | NO |
| 5. | Are the doors easy to open? | YES |
| 6. | Are the doors at least 800 mm wide? | YES |

(c) Internal

- | | | |
|----|---|-----|
| 1. | How far is the polling station from the entrance? | 5 m |
| 2. | If there are corridors/lobbies, are they at least 800mm wide? | YES |
| 3. | Are there any internal stairs to polling station? | NO |
| 4. | Is there a chair (with arms) available? | YES |
| 5. | Are floor surfaces non-slip? | YES |
| 6. | Is lighting sufficient (non-glare)? | YES |

2. COMMENTS BY RETURNING OFFICER

VOTING IS IN THE CHURCH. A CAR PARK FOR ALL VOTERS IS 30M AWAY.

POLLING PLACE AUDIT**POLLING PLACE: ST MARGARET'S CHURCH HALL, 17 DALHOUSIE ROAD****REFERENCE NO 42****1. ACCESS AUDIT****(a) Car Parking**

- | | | |
|----|--|-----|
| 1. | Is parking available nearby and with ample room to open car door (i.e. 3.4m)? | YES |
| 2. | Alternatively, is there a dropping off zone again with ample room to open door? | N/A |
| 3. | Is there a dropped kerb to allow access to main door from parking/dropping off area? | YES |
| 4. | Are the road/pavement surfaces level and of good quality (e.g. no potholed)? | YES |

(b) Access to Premises

- | | | |
|----|--|-----|
| 1. | Is the access on the flat? | YES |
| 2. | <u>Are there any steps to main door (if yes - how many)?</u> | NO |
| 3. | If there are any steps, is there a handrail? | N/A |
| 4. | Is there a ramp? (Gradient 1:) | NO |
| 5. | Are the doors easy to open? | YES |
| 6. | Are the doors at least 800 mm wide? | YES |
- (c) Internal**
- | | | |
|----|---|-----|
| 1. | How far is the polling station from the entrance? | 5 m |
| 2. | If there are corridors/lobbies, are they at least 800mm wide? | YES |
| 3. | Are there any internal stairs to polling station? | NO |
| 4. | Is there a chair (with arms) available? | YES |
| 5. | Are floor surfaces non-slip? | YES |
| 6. | Is lighting sufficient (non-glare)? | YES |

2. COMMENTS BY RETURNING OFFICER

VOTING IS IN THE HALL. PARKING AVAILABLE ON GUTHRIE TERRACE. ACCESS FROM GUTHRIE TERRACE TO HALL IS LEVEL WITH A DROPPED KERB. ALTERNATIVE ACCESS VIA DALHOUSIE ROAD HAS 2 STEPS. PARKING FOR 4 CARS ON DALHOUSIE ROAD.

POLLING PLACE AUDIT**POLLING PLACE: BARNHILL PRIMARY SCHOOL, FALKLAND CRESCENT****REFERENCE NO 43****1. ACCESS AUDIT****(a) Car Parking**

- | | | |
|----|--|-----|
| 1. | Is parking available nearby and with ample room to open car door (i.e. 3.4m)? | YES |
| 2. | Alternatively, is there a dropping off zone again with ample room to open door? | N/A |
| 3. | Is there a dropped kerb to allow access to main door from parking/dropping off area? | NO |
| 4. | Are the road/pavement surfaces level and of good quality (e.g. no potholed)? | YES |

(b) Access to Premises

- | | | |
|----|--|-----|
| 1. | Is the access on the flat? | YES |
| 2. | <u>Are there any steps to main door (if yes - how many)?</u> | NO |
| 3. | If there are any steps, is there a handrail? | N/A |
| 4. | Is there a ramp? (Gradient 1: 4) | YES |
| 5. | Are the doors easy to open? | YES |
| 6. | Are the doors at least 800 mm wide? | YES |

(c) Internal

- | | | |
|----|---|-----|
| 1. | How far is the polling station from the entrance? | |
| 2. | If there are corridors/lobbies, are they at least 800mm wide? | YES |
| 3. | Are there any internal stairs to polling station? | NO |
| 4. | Is there a chair (with arms) available? | YES |
| 5. | Are floor surfaces non-slip? | YES |
| 6. | Is lighting sufficient (non-glare)? | YES |

2. COMMENTS BY RETURNING OFFICER

VOTING IS IN THE MAIN HALL. INTERNAL DOORS TO BE WEDGED OPEN. PARKING IN CAR PARK AT MAIN GATE. 1 SPACE RESERVED FOR DISABLED. PERMANENT RAMP TO MAIN ENTRANCE.

POLLING PLACE AUDIT**POLLING PLACE: BROUGHTY FERRY LAWN TENNIS CLUB, ELCHO DRIVE****REFERENCE NO 91****1. ACCESS AUDIT****(a) Car Parking**

- | | | |
|----|--|-----|
| 1. | Is parking available nearby and with ample room to open car door (i.e. 3.4m)? | YES |
| 2. | Alternatively, is there a dropping off zone again with ample room to open door? | N/A |
| 3. | Is there a dropped kerb to allow access to main door from parking/dropping off area? | YES |
| 4. | Are the road/pavement surfaces level and of good quality (e.g. no potholed)? | YES |

(b) Access to Premises

- | | | |
|----|--|-----|
| 1. | Is the access on the flat? | YES |
| 2. | <u>Are there any steps to main door (if yes - how many)?</u> | NO |
| 3. | If there are any steps, is there a handrail? | N/A |
| 4. | Is there a ramp? (Gradient 1:) | NO |
| 5. | Are the doors easy to open? | YES |
| 6. | Are the doors at least 800 mm wide? | YES |
- (c) Internal**
- | | | |
|----|---|-----|
| 1. | How far is the polling station from the entrance? | 5 m |
| 2. | If there are corridors/lobbies, are they at least 800mm wide? | YES |
| 3. | Are there any internal stairs to polling station? | NO |
| 4. | Is there a chair (with arms) available? | YES |
| 5. | Are floor surfaces non-slip? | YES |
| 6. | Is lighting sufficient (non-glare)? | YES |

2. COMMENTS BY RETURNING OFFICER

VOTING IN PLAYERS LOUNGE. INTERNAL DOORS TO BE WEDGED. AMPLE CAR PARKING ADJACENT TO BUILDING.

POLLING PLACE AUDIT**POLLING PLACE: FORTHILL PRIMARY SCHOOL, FINTRY PLACE****REFERENCE NO 37****1. ACCESS AUDIT****(a) Car Parking**

- | | | |
|----|--|-----|
| 1. | Is parking available nearby and with ample room to open car door (i.e. 3.4m)? | YES |
| 2. | Alternatively, is there a dropping off zone again with ample room to open door? | N/A |
| 3. | Is there a dropped kerb to allow access to main door from parking/dropping off area? | YES |
| 4. | Are the road/pavement surfaces level and of good quality (e.g. no potholed)? | YES |

(b) Access to Premises

- | | | |
|----|--|-------|
| 1. | Is the access on the flat? | NO |
| 2. | <u>Are there any steps to main door (if yes - how many)?</u> | YES 1 |
| 3. | If there are any steps, is there a handrail? | YES 1 |
| 4. | Is there a ramp? (Gradient 1: 13) | YES |
| 5. | Are the doors easy to open? | YES |
| 6. | Are the doors at least 800 mm wide? | YES |
- (c) Internal**
- | | | |
|----|---|-----|
| 1. | How far is the polling station from the entrance? | 5 m |
| 2. | If there are corridors/lobbies, are they at least 800mm wide? | YES |
| 3. | Are there any internal stairs to polling station? | NO |
| 4. | Is there a chair (with arms) available? | YES |
| 5. | Are floor surfaces non-slip? | YES |
| 6. | Is lighting sufficient (non-glare)? | YES |

2. COMMENTS BY RETURNING OFFICER

VOTING IS IN ASSEMBLY HALL. TEMPORARY RAMP PROVIDED. 7 PARKING SPACES PLUS 2 SPACES FOR DISABLED VOTERS ADJACENT TO MAIN ENTRANCE. ALSO A DROP OFF AREA CAPABLE OF TAKING 6 VEHICLES. APPROX 100M FROM FRONT ENTRANCE.

POLLING PLACE AUDIT**POLLING PLACE: EASTERN PRIMARY SCHOOL, WHINNYBRAE****REFERENCE NO 39****1. ACCESS AUDIT****(a) Car Parking**

- | | | |
|----|--|-----|
| 1. | Is parking available nearby and with ample room to open car door (i.e. 3.4m)? | YES |
| 2. | Alternatively, is there a dropping off zone again with ample room to open door? | N/A |
| 3. | Is there a dropped kerb to allow access to main door from parking/dropping off area? | N/A |
| 4. | Are the road/pavement surfaces level and of good quality (e.g. no potholed)? | YES |

(b) Access to Premises

- | | | |
|----|--|-------|
| 1. | Is the access on the flat? | NO |
| 2. | <u>Are there any steps to main door (if yes - how many)?</u> | YES 5 |
| 3. | If there are any steps, is there a handrail? | NO |
| 4. | Is there a ramp? (Gradient 1:) | NO |
| 5. | Are the doors easy to open? | YES |
| 6. | Are the doors at least 800 mm wide? | YES |

(c) Internal

- | | | |
|----|---|------|
| 1. | How far is the polling station from the entrance? | 20 m |
| 2. | If there are corridors/lobbies, are they at least 800mm wide? | YES |
| 3. | Are there any internal stairs to polling station? | NO |
| 4. | Is there a chair (with arms) available? | NO |
| 5. | Are floor surfaces non-slip? | YES |
| 6. | Is lighting sufficient (non-glare)? | YES |

2. COMMENTS BY RETURNING OFFICER

VOTING IS IN THE GYM. PERMANENT RAMPED ACCESS AVAILABLE FROM PLAYGROUND. ADDITIONAL EXTERNAL SIGNAGE NEEDED. 1 DISABLED CAR PARKING SPACE DESIGNATED AT MAIN GATE FOR VEHICULAR ACCESS.

POLLING PLACE AUDIT**POLLING PLACE: ST AIDANS CHURCH HALL, ST VINCENT STREET, BROUGHTY FERRY****REFERENCE NO 40****1. ACCESS AUDIT****(a) Car Parking**

- | | | |
|----|--|-----|
| 1. | Is parking available nearby and with ample room to open car door (i.e. 3.4m)? | YES |
| 2. | Alternatively, is there a dropping off zone again with ample room to open door? | N/A |
| 3. | Is there a dropped kerb to allow access to main door from parking/dropping off area? | N/A |
| 4. | Are the road/pavement surfaces level and of good quality (e.g. no potholed)? | YES |

(b) Access to Premises

- | | | |
|----|--|-----|
| 1. | Is the access on the flat? | YES |
| 2. | <u>Are there any steps to main door (if yes - how many)?</u> | NO |
| 3. | If there are any steps, is there a handrail? | N/A |
| 4. | Is there a ramp? (Gradient 1:) | NO |
| 5. | Are the doors easy to open? | YES |
| 6. | Are the doors at least 800 mm wide? | YES |
- (c) Internal**
- | | | |
|----|---|-----|
| 1. | How far is the polling station from the entrance? | 5 m |
| 2. | If there are corridors/lobbies, are they at least 800mm wide? | YES |
| 3. | Are there any internal stairs to polling station? | NO |
| 4. | Is there a chair (with arms) available? | YES |
| 5. | Are floor surfaces non-slip? | YES |
| 6. | Is lighting sufficient (non-glare)? | YES |

2. COMMENTS BY RETURNING OFFICER

VOTING IS IN THE NORTH HALL. CAR PARK ADJACENT - NO DROPPED KERB NECESSARY.
 CAR PARK SLABBING CRACKED.

POLLING PLACE AUDIT**POLLING PLACE: GROVE ACADEMY, CLAYPOTTS ROAD, BROUGHTY FERRY****REFERENCE NO 38****1. ACCESS AUDIT****(a) Car Parking**

- | | | |
|----|--|-----|
| 1. | Is parking available nearby and with ample room to open car door (i.e. 3.4m)? | YES |
| 2. | Alternatively, is there a dropping off zone again with ample room to open door? | YES |
| 3. | Is there a dropped kerb to allow access to main door from parking/dropping off area? | YES |
| 4. | Are the road/pavement surfaces level and of good quality (e.g. no potholed)? | YES |

(b) Access to Premises

- | | | |
|----|--|-----|
| 1. | Is the access on the flat? | YES |
| 2. | <u>Are there any steps to main door (if yes - how many)?</u> | NO |
| 3. | If there are any steps, is there a handrail? | N/A |
| 4. | Is there a ramp? (Gradient 1:) | NO |
| 5. | Are the doors easy to open? | YES |
| 6. | Are the doors at least 800 mm wide? | YES |

(c) Internal

- | | | |
|----|---|-----|
| 1. | How far is the polling station from the entrance? | 1 m |
| 2. | If there are corridors/lobbies, are they at least 800mm wide? | YES |
| 3. | Are there any internal stairs to polling station? | NO |
| 4. | Is there a chair (with arms) available? | YES |
| 5. | Are floor surfaces non-slip? | YES |
| 6. | Is lighting sufficient (non-glare)? | YES |

2. COMMENTS BY RETURNING OFFICER

VOTING IS IN THE SPORTS HALL. PARKING IN PLAYGROUND. LIMITED PARKING ON CLAYPOTTS ROAD.

POLLING PLACE AUDIT**POLLING PLACE: CRAIGIEBARNES PRIMARY SCHOOL, BRINGTON ROAD****REFERENCE NO 16****1. ACCESS AUDIT****(a) Car Parking**

- | | | |
|----|--|-----|
| 1. | Is parking available nearby and with ample room to open car door (i.e. 3.4m)? | YES |
| 2. | Alternatively, is there a dropping off zone again with ample room to open door? | N/A |
| 3. | Is there a dropped kerb to allow access to main door from parking/dropping off area? | YES |
| 4. | Are the road/pavement surfaces level and of good quality (e.g. no potholed)? | YES |

(b) Access to Premises

- | | | |
|----|--|-----|
| 1. | Is the access on the flat? | YES |
| 2. | <u>Are there any steps to main door (if yes - how many)?</u> | NO |
| 3. | If there are any steps, is there a handrail? | N/A |
| 4. | Is there a ramp? (Gradient 1: 35) | YES |
| 5. | Are the doors easy to open? | YES |
| 6. | Are the doors at least 800 mm wide? | YES |
- (c) Internal**
- | | | |
|----|---|------|
| 1. | How far is the polling station from the entrance? | 12 m |
| 2. | If there are corridors/lobbies, are they at least 800mm wide? | YES |
| 3. | Are there any internal stairs to polling station? | NO |
| 4. | Is there a chair (with arms) available? | YES |
| 5. | Are floor surfaces non-slip? | YES |
| 6. | Is lighting sufficient (non-glare)? | YES |

2. COMMENTS BY RETURNING OFFICER

VOTING IS IN THE RUMPUS ROOM AND BIG HALL. PARKING AVAILABLE IN PLAYGROUND. 1 SPACE RESERVED FOR DISABLED VOTER 20 M FROM ENTRANCE DOOR USED.

POLLING PLACE AUDIT**POLLING PLACE: FORTHILL SHELTERED COMMUNAL LOUNGE, 3A FORTHILL DRIVE****REFERENCE NO 86****1. ACCESS AUDIT****(a) Car Parking**

- | | | |
|----|--|-----|
| 1. | Is parking available nearby and with ample room to open car door (i.e. 3.4m)? | NO |
| 2. | Alternatively, is there a dropping off zone again with ample room to open door? | YES |
| 3. | Is there a dropped kerb to allow access to main door from parking/dropping off area? | YES |
| 4. | Are the road/pavement surfaces level and of good quality (e.g. no potholed)? | YES |

(b) Access to Premises

- | | | |
|----|--|-----|
| 1. | Is the access on the flat? | YES |
| 2. | <u>Are there any steps to main door (if yes - how many)?</u> | NO |
| 3. | If there are any steps, is there a handrail? | N/A |
| 4. | Is there a ramp? (Gradient 1:) | NO |
| 5. | Are the doors easy to open? | YES |
| 6. | Are the doors at least 800 mm wide? | YES |

(c) Internal

- | | | |
|----|---|------|
| 1. | How far is the polling station from the entrance? | 10 m |
| 2. | If there are corridors/lobbies, are they at least 800mm wide? | YES |
| 3. | Are there any internal stairs to polling station? | NO |
| 4. | Is there a chair (with arms) available? | YES |
| 5. | Are floor surfaces non-slip? | YES |
| 6. | Is lighting sufficient (non-glare)? | YES |

2. COMMENTS BY RETURNING OFFICER

VOTING IN LOUNGE. LIMITED PARKING ON FORTHILL DRIVE.

POLLING PLACE AUDIT**POLLING PLACE: BARNHILL COMMUNITY CENTRE, CAMPFIELD SQUARE****REFERENCE NO 92****1. ACCESS AUDIT****(a) Car Parking**

- | | | |
|----|--|-----|
| 1. | Is parking available nearby and with ample room to open car door (i.e. 3.4m)? | YES |
| 2. | Alternatively, is there a dropping off zone again with ample room to open door? | N/A |
| 3. | Is there a dropped kerb to allow access to main door from parking/dropping off area? | YES |
| 4. | Are the road/pavement surfaces level and of good quality (e.g. no potholed)? | YES |

(b) Access to Premises

- | | | |
|----|--|-----|
| 1. | Is the access on the flat? | YES |
| 2. | <u>Are there any steps to main door (if yes - how many)?</u> | NO |
| 3. | If there are any steps, is there a handrail? | N/A |
| 4. | Is there a ramp? (Gradient 1:) | NO |
| 5. | Are the doors easy to open? | YES |
| 6. | Are the doors at least 800 mm wide? | YES |

(c) Internal

- | | | |
|----|---|-----|
| 1. | How far is the polling station from the entrance? | 5m |
| 2. | If there are corridors/lobbies, are they at least 800mm wide? | YES |
| 3. | Are there any internal stairs to polling station? | NO |
| 4. | Is there a chair (with arms) available? | NO |
| 5. | Are floor surfaces non-slip? | YES |
| 6. | Is lighting sufficient (non-glare)? | YES |

2. COMMENTS BY RETURNING OFFICER

VOTING IS IN THE MAIN HALL. AMPLE PARKING IN SHOPPING CENTRE CAR PARK. 5 SPACES FOR DISABLED. DROPPED KERB AT 3 OF THOSE SPACES.